EU Safety Gate Alerts (Aug 2022)

### **Recall Summary – European Toys**

**ESTC** NEWSLETTER

|              |           |             |  | EU Safety Gate A                               |                   |
|--------------|-----------|-------------|--|--|-------------------|
| Alert No.    | Notifying | Product     | Product  | Hazard/ Risk                                   | Measures          |
|              | Country   |             | Photo  |  | Adopted           |
| A11/00098/22 | Poland    | Infant      | i 👶 👶  | Strangulation                                  | The product       |
|              |           | swing /     | made Mol 010 made Mol 010 made Mol 010 solar Mol 010 | When the product is not in use, the seat       | owners will       |
|              |           | rocker      |  | belts (tethered straps) can hang freely        | receive a strap   |
|              |           |             |  | under the seat. An infant may crawl under      | fastener that     |
|              |           | (Country of |  | the seat and become entangled in them,         | attaches to the   |
|              |           | Origin:     |  | leading to strangulation. The product does     | back of the       |
|              |           | China)      |  | not comply with the requirements of the        | products seat.    |
|              |           |             |  | General Product Safety Directive.              |                   |
| A12/01105/22 | Czechia   | Battery     |  | Choking, Injuries                              | Withdrawal of the |
|              |           | operated    |  | The battery compartment is easily              | product from the  |
|              |           | toy         |  | opened/broken, leaving the button batteries    | market            |
|              |           |             |  | accessible. A child could put them in the      |                   |
|              |           | (Country of |  | mouth, which could cause injury to the         |                   |
|              |           | Origin:     |  | child's gastrointestinal tract or choking. The |                   |
|              |           | China)      |  | product does not comply with the               |                   |
|              |           |             |  | requirements of the Toy Safety Directive       |                   |
|              |           |             |  | nor with European standard EN 62115.           |                   |
| A12/01106/22 | Czechia   | Battery     |  | Environment                                    | Withdrawal of the |
|              |           | operated    |  | The solder has an excessive concentration      | product from the  |
|              |           | toy         |  | of lead (measured value up to 68.9% by         | market            |
|              |           |             |  | weight). Lead poses a risk to the              |                   |
|              |           | (Country of |  | environment. The product does not comply       |                   |
|              |           | Origin:     |  | with the requirements of the Directive on      |                   |
|              |           | China)      |  | the restriction of the use of certain          |                   |
|              |           |             |  | hazardous substances in electrical and         |                   |
|              |           |             |  | electronic equipment (RoHS 2 Directive).       |                   |
| A12/01107/22 | Czechia   | Battery     |  | Environment                                    | Recall of the     |
|              |           | operated    |  | The solder has an excessive concentration      | product from end  |
|              |           | toy         |  | of lead (measured value up to 65.8% by         | users             |
|              |           |             |  | weight). Lead poses a risk to the              |                   |
|              |           | (Country of |  | environment. The product does not comply       |                   |
|              |           | Origin:     |  | with the requirements of the Directive on      |                   |
|              |           | China)      |  | the restriction of the use of certain          |                   |
|              |           |             |  | hazardous substances in electrical and         |                   |
|              |           |             |  | electronic equipment (RoHS 2 Directive).       |                   |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| A12/01110/22 | Poland | Plastic<br>doll<br>(Country of<br>Origin:<br>China)    |                | Chemical<br>The toy contains bis (2-ethylhexyl)<br>phthalate (DEHP), measured value up to<br>26.6% by weight. This phthalate may harm<br>the health of children, possibly causing<br>damage to the reproductive system. The<br>product does not comply with the REACH<br>Regulation.   | Destruction of the<br>product                   |
|--------------|--------|--|----------------|--|---|
| A12/01116/22 | France | Beach ball<br>(Country of<br>Origin:<br>China)         | E CENTRO O     | Choking, Suffocation<br>The product has a small detachable part<br>(air stopper plug), which a child can easily<br>access, put in the mouth and choke on.<br>Furthermore, the presence of a<br>non-permeable plastic bag poses a risk of<br>suffocation. The product does not comply<br>with the requirement of the Toy Safety<br>Directive nor with the European standard<br>EN 71-1.   | Recall of the<br>product from end<br>users      |
| A12/01119/22 | Poland | Expandabl<br>e toy<br>(Country of<br>Origin:<br>China) | SURPRISE SEDER | Choking, Injuries<br>The plastic spider breaks easily and<br>releases soft plastic figurines which expand<br>more than 50% in size when in contact with<br>water. If a child puts it in the mouth or<br>swallows it, the contact with saliva or<br>stomach liquids will cause the figurines to<br>expand, which can result in occlusion of the<br>respiratory track or intestinal blockage. The<br>product does not comply with the<br>requirements of the Toy Safety Directive<br>nor with the European standard EN 71-1. | Withdrawal of the<br>product from the<br>market |

| A12/01120/22 | Poland | Expandable   | A MARK A DOMINI | Choking, Injuries                               | Warning           |
|--------------|--------|--------------|-----------------|---|-------------------|
|              |        | toy          | ATHEN BOOM      | The egg breaks easily and releases an           | consumers of the  |
|              |        |              | O AMUSINE       | alien figurine which expands more than          | risks             |
|              |        | (Country of  | ORUNAV          | 50% in size when in contact with water. If a    |                   |
|              |        | Origin:      |                 | child puts it in the mouth or swallows it, the  |                   |
|              |        | China)       | SAMA I          | contact with saliva or stomach liquids will     |                   |
|              |        |              | GROWING PET     | cause the figurine to expand, which can         |                   |
|              |        |              |                 | result in occlusion of the respiratory track or |                   |
|              |        |              | Swallow         | intestinal blockage. The product does not       |                   |
|              |        |              |                 | comply with the requirements of the Toy         |                   |
|              |        |              |                 | Safety Directive nor with the European          |                   |
|              |        |              |                 | standard EN 71-1.                               |                   |
| A12/01121/22 | Poland | Expandable   |                 | Choking, Injuries                               | Warning           |
|              |        | toy          |                 | The egg easily breaks and releases a turtle     | consumers of the  |
|              |        |              | E               | figurine which expands more than 50% in         | risks             |
|              |        | (Country of  |                 | size when in contact with water. If a child     |                   |
|              |        | Origin:      | GROWING         | puts it in the mouth or swallows it, the        |                   |
|              |        | Unknown)     | EGG             | contact with saliva or stomach liquids will     |                   |
|              |        |              |                 | cause the figurine to expand, which can         |                   |
|              |        |              |                 | result in occlusion of the respiratory track or |                   |
|              |        |              |                 | intestinal blockage. The product does not       |                   |
|              |        |              |                 | comply with the requirements of the Toy         |                   |
|              |        |              |                 | Safety Directive nor with the European          |                   |
|              |        |              |                 | standard EN 71-1.                               |                   |
| A12/01125/22 | Poland | Plastic doll | *               | Chemical  | Withdrawal of the |
|              |        |              | -F) 5           | The toy contains an excessive                   | product from the  |
|              |        | (Country of  |                 | concentration of bis (2-ethylhexyl) phthalate   | market            |
|              |        | Origin:      |                 | (DEHP) and dibutyl phthalate (DBP)              |                   |
|              |        | China)       |                 | (measured values up to 7.8% and 1.9% by         |                   |
|              |        |              |                 | weight, respectively). These phthalates         |                   |
|              |        |              |                 | may harm the health of children, possibly       |                   |
|              |        |              |                 | causing damage to their reproductive            |                   |
|              |        |              |                 | system. The product does not comply with        |                   |
|              |        |              | 1               | the REACH Regulation.                           |                   |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| A12/01126/22 | Czechia | Battery     | B      | Environment                                 | Withdrawal of the |
|--------------|---------|-------------|--------|---|-------------------|
|              |         | operated    | TALE   | The solder contains an excessive amount     | product from the  |
|              |         | toy         | Press. | of lead (measured value up to 70.1% by      | market            |
|              |         |             |        | weight) and cadmium (measured value up      |                   |
|              |         | (Country of |        | to 0.13 % cadmium by weight). Lead and      |                   |
|              |         | Origin:     |        | cadmium pose a risk to the environment.     |                   |
|              |         | China)      |        | The product does not comply with the        |                   |
|              |         |             |        | requirements of the Directive on the        |                   |
|              |         |             |        | restriction of the use of certain hazardous |                   |
|              |         |             |        | substances in electrical and electronic     |                   |
|              |         |             |        | equipment (RoHS 2 Directive).               |                   |
|              |         |             |        |   |                   |
| A12/01127/22 | Czechia | Battery     |        | Environment                                 | Withdrawal of the |
|              |         | operated    |        | The solder contains an excessive amount     | product from the  |
|              |         | toy         |        | of lead (measured value up to 62.5% by      | market            |
|              |         |             |        | weight) and cadmium (measured value up      |                   |
|              |         | (Country of |        | to 0.08%). Lead and cadmium pose a risk     |                   |
|              |         | Origin:     |        | to the environment. The product does not    |                   |
|              |         | China)      |        | comply with the requirements of the         |                   |
|              |         |             |        | Directive on the restriction of the use of  |                   |
|              |         |             |        | certain hazardous substances in electrical  |                   |
|              |         |             |        | and electronic equipment (RoHS 2            |                   |
|              |         |             |        | Directive).                                 |                   |
| A12/01128/22 | Czechia | Battery     |        | Environment                                 | Stop of sales     |
|              |         | operated    | 1 1000 | The solder contains an excessive amount     |                   |
|              |         | toy         |        | of lead (measured value up to 57.5% by      |                   |
|              |         |             |        | weight). Lead poses a risk to the           |                   |
|              |         | (Country of |        | environment. The product does not comply    |                   |
|              |         | Origin:     |        | with the requirements of the Directive on   |                   |
|              |         | China)      |        | the restriction of the use of certain       |                   |
|              |         |             |        | hazardous substances in electrical and      |                   |
|              |         |             |        | electronic equipment (RoHS 2 Directive).    |                   |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.



| A12/01138/22 | Czechia     | Battery     |   | Environment                                    | Withdrawal of the |
|--------------|-------------|-------------|---|--|-------------------|
|              |             | operated    |   | The solder contains an excessive amount        | product from the  |
|              |             | toy         | B   | of lead (measured value up to 72.3% by         | market            |
|              |             |             |   | weight) and cadmium (measured value up         |                   |
|              |             | (Country of |   | to 0.06%).Lead and cadmium pose a risk to      |                   |
|              |             | Origin:     |   | the environment. The product does not          |                   |
|              |             | China)      |   | comply with the requirements of the            |                   |
|              |             |             |   | Directive on the restriction of the use of     |                   |
|              |             |             |   | certain hazardous substances in electrical     |                   |
|              |             |             |   | and electronic equipment (RoHS 2               |                   |
|              |             |             |   | Directive).                                    |                   |
| A12/01139/22 | The         | Squeeze     | 12/0886   | Microbiological                                | Recall of the     |
|              | Netherlands | toy         |   | The toy is not resistant enough to leakage     | product from end  |
|              |             |             |   | and the liquid in the toy is contaminated      | users             |
|              |             | (Country of |   | with aerobic microorganisms (measured          |                   |
|              |             | Origin:     |   | value up to 300,000 CFU/g). As a               |                   |
|              |             | Germany)    |   | consequence, fluid may leak out, infecting     |                   |
|              |             |             |   | the user. The product does not comply with     |                   |
|              |             |             |   | the requirements of the Toy Safety             |                   |
|              |             |             |   | Directive nor with the European standard       |                   |
|              |             |             |   | EN 71-1.                                       |                   |
| A12/01142/22 | Lithuania   | Toy-helico  |   | Choking, Injuries                              | Withdrawal of the |
|              |             | pter with   |   | Small parts (wheels of the helicopter) can     | product from the  |
|              |             | sweets      | PLASH PASHA<br>MILLICOMTINE   | easily detach from the toy. A small child      | market            |
|              |             |             |   | may put them in the mouth and choke. As        |                   |
|              |             | (Country of |   | the small parts are sharp they can also        |                   |
|              |             | Origin:     |   | cause injuries. The product does not           |                   |
|              |             | China)      |   | comply with the requirements of the Toy        |                   |
|              |             |             |   | Safety Directive nor with the European         |                   |
|              |             |             |   | standard EN 71.                                |                   |
| A12/01143/22 | Czechia     | Battery     | THE REAL PROPERTY OF THE REAL | Environment                                    | Withdrawal of the |
|              |             | operated    | RE  | The solder contains an excessive amount        | product from the  |
|              |             | toy         |   | of lead (measured value up to 48.8% by         | market            |
|              |             |             |   | weight) and cadmium (measured value up         |                   |
|              |             | (Country of |   | to 0.05% by weight). Lead and cadmium          |                   |
|              |             | Origin:     |   | pose a risk to the environment. The product    |                   |
|              |             | China)      |   | does not comply with the requirements of       |                   |
|              |             |             |   | the Directive on the restriction of the use of |                   |
|              |             |             |   | certain hazardous substances in electrical     |                   |
|              |             |             |   | and electronic equipment (RoHS 2               |                   |
|              |             |             |   | Directive).                                    |                   |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| A12/01148/22 | Finland | Puffer toy<br>(Country of<br>Origin:<br>China)             |                                | <b>Choking</b><br>The eyes of the toy can easily detach. A child may put them in the mouth and choke.<br>The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.  | Stop of sales                                   |
|--------------|---------|--|--------------------------------|---|---|
| A12/01165/22 | Czechia | Inflatable<br>armbands<br>(Country of<br>Origin:<br>China) |                                | <b>Chemical</b><br>The plastic material of the product contains<br>an excessive concentration of bis<br>(2-ethylhexyl) phthalate (DEHP) (measured<br>value up to 18.6% by weight). This<br>phthalate may harm the health of children,<br>causing possible damage to the<br>reproductive system. The product does not<br>comply with the REACH Regulation. | Withdrawal of the<br>product from the<br>market |
| A12/01166/22 | France  | Fancy<br>dress<br>(Country of<br>Origin:<br>China)         | Baby Honey Boar<br>REF. 409233 | <b>Choking</b><br>Small parts (nose, right eye, left eye) can<br>easily detach from the toy. As a<br>consequence, a small child may put them in<br>the mouth and choke. The product does not<br>comply with the requirements of the Toy<br>Safety Directive nor with the European<br>standard EN 71-1.  | Recall of the<br>product from end<br>users      |
| A12/01171/22 | Germany | Muslin<br>cloths<br>(Country of<br>Origin:<br>Germany)     |                                | <b>Chemical</b><br>The product contains an excessive amount<br>of formaldehyde (measured value<br>235 mg/kg). Formaldehyde is a skin<br>sensitizer and can trigger allergic reactions<br>and may cause cancer. The product does<br>not comply with the REACH Regulation.  | Stop of sales                                   |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| A12/01185/22 | Poland    | Plastic toy             |             | Chemical                                       | Withdrawal of the  |
|--------------|-----------|-------------------------|-------------|--|--------------------|
|              |           |                         |             | The battery compartment cover can be           | product from the   |
|              |           | (Country of             |             | easily opened (if the toy is dropped),         | market             |
|              |           | Origin: China)          | SMOKE TRAIN | leaving batteries accessible. A child may      |                    |
|              |           |                         |             | put them in the mouth and suck on them.        |                    |
|              |           |                         |             | If the batteries leak, this liquid could cause |                    |
|              |           |                         |             | damage to the gastrointestinal tract. The      |                    |
|              |           |                         |             | product does not comply with the               |                    |
|              |           |                         |             | requirements of the Toy Safety Directive       |                    |
|              |           |                         |             | nor with the European standard EN 62115.       |                    |
| A12/01187/22 | Finland   | Police toy set          |             | Chemical                                       | Import rejected at |
|              |           |                         |             | The transparent plastic material of the black  | border             |
|              |           | (Country of             |             | case for the card holder contains an           |                    |
|              |           | Origin: China)          |             | excessive concentration of bis                 |                    |
|              |           |                         |             | (2-ethylhexyl) phthalate (DEHP) (measured      |                    |
|              |           |                         |             | value up to 12% by weight). This phthalate     |                    |
|              |           |                         |             | may harm the health of children, possibly      |                    |
|              |           |                         |             | causing damage to their reproductive           |                    |
|              |           |                         |             | system The product does not comply with        |                    |
|              |           |                         |             | the REACH regulation.                          |                    |
| A12/01192/22 | Lithuania | Toy-helicopter          |             | Choking, Injuries                              | Withdrawal of the  |
|              |           | with sweets             | A COL       | Small parts (wheels of the helicopter) can     | product from the   |
|              |           |                         |             | easily detach from the toy. A small child      | market             |
|              |           | (Country of             |             | may put them in the mouth and choke. As        |                    |
|              |           | Origin: <b>Turkey</b> ) |             | the small parts are sharp they can also        |                    |
|              |           |                         |             | cause injuries. The product does not           |                    |
|              |           |                         |             | comply with the requirements of the Toy        |                    |
|              |           |                         |             | Safety Directive nor with the European         |                    |
|              |           |                         |             | standard EN 71.                                |                    |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| A12/01208/22 | Poland | Soft toy    |  | Chemical, Choking, Suffocation                 | Warning            |
|--------------|--------|-------------|--|--|--------------------|
|              |        |             |  | Small part (metal zipper) may easily detach    | consumers of the   |
|              |        | (Country of |  | from the toy. The fibrous stuffing material of | risks              |
|              |        | Origin:     | NTAL DA                                  | the toy is easily accessible. A small child    |                    |
|              |        | China)      |  | may put the small part and/or the stuffing     |                    |
|              |        |             |  | material in the mouth and choke. Moreover,     |                    |
|              |        |             |  | the plastic of the packaging is too thin. If a |                    |
|              |        |             |  | child plays with the packaging, the plastic    |                    |
|              |        |             |  | can cover the mouth and nose, causing the      |                    |
|              |        |             |  | child to suffocate. Furthermore, the battery   |                    |
|              |        |             |  | compartment can be easily opened, leaving      |                    |
|              |        |             |  | the button cell batteries accessible. A child  |                    |
|              |        |             |  | may put them in the mouth and ingest           |                    |
|              |        |             |  | them, which may lead to choking if they        |                    |
|              |        |             |  | enter the airways, or could cause damage       |                    |
|              |        |             |  | to the gastrointestinal tract. The product     |                    |
|              |        |             |  | does not comply with the requirements of       |                    |
|              |        |             |  | the Toy Safety Directive nor with the          |                    |
|              |        |             |  | European standards EN 71-1 & EN 62115.         |                    |
| A12/01217/22 | Poland | Toy slime   |  | Chemical                                       | Destruction of the |
|              |        |             | ATT B                                    | The migration of boron from the toy is too     | product            |
|              |        | (Country of | C. C | high (measured value: up to 1536 mg/kg).       |                    |
|              |        | Origin:     |  | Ingestion or contact with an excessive         |                    |
|              |        | China)      |  | quantity of boron may harm the health of       |                    |
|              |        |             |  | children by damaging their reproductive        |                    |
|              |        |             |  | system. In addition, the toy contains an       |                    |
|              |        |             |  | excessive amount of cadmium (measured          |                    |
|              |        |             |  | value: up to 0.80 mg/kg). Cadmium is           |                    |
|              |        |             |  | harmful to human health because it             |                    |
|              |        |             |  | accumulates in the body, can damage the        |                    |
|              |        |             |  | kidneys and bones, and it may cause            |                    |
|              |        |             |  | cancer. The product does not comply with       |                    |
|              |        |             |  | the requirements of the Toy Safety             |                    |
|              |        |             |  | Directive nor with the European standard       |                    |
|              |        |             |  | EN 71-3.                                       |                    |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| A12/01226/22 | France | Toy car     |     | Choking                                       | Recall  | of   | the |
|--------------|--------|-------------|-----|---|---------|------|-----|
|              |        | circuit     |     | The wheels of the wooden cars supplied        | product | from | end |
|              |        |             |     | with the toy car circuit generate small parts | users   |      |     |
|              |        | (Country of |     | (wooden wheel fragments). Small children      |         |      |     |
|              |        | Origin:     |     | may put them in the mouth and choke. The      |         |      |     |
|              |        | Belgium)    |     | product does not comply with the              |         |      |     |
|              |        |             |     | requirements of the Toy Safety Directive      |         |      |     |
|              |        |             |     | nor with the European standard EN 71-1.       |         |      |     |
| A12/01230/22 | Sweden | Children's  |     | Injuries                                      | Recall  | of   | the |
|              |        | crib        |     | One bedside can be dislodged                  | product | from | end |
|              |        |             |     | unintentionally. A child may fall off the bed | users   |      |     |
|              |        | (Country of | y v | and suffer injuries. The product does not     |         |      |     |
|              |        | Origin:     |     | comply with the requirements of the           |         |      |     |
|              |        | Poland)     |     | General Product Safety Directive.             |         |      |     |

### Safety Gate: the EU rapid alert system for dangerous non-food products

"Safety Gate", the EU rapid alert system (formerly known as 'RAPEX'), enables the rapid exchange of information between **31 European countries** and the European Commission on non- food dangerous products found on the market posing a risk to health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports. The measures taken in the notifying country in order to restrict their marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

### **Recall Summary – US Toys / Children's Products**

**ESTC** NEWSLETTER

|               |                      |              |                  | CPS                                    | C Recall List (Aug 2022)        |
|---------------|----------------------|--------------|------------------|--|---------------------------------|
| Recall<br>No. | Notifying<br>Country | Product      | Product<br>Photo | Hazard/ Risk                           | Remedy                          |
| 22-200        | USA                  | 4moms        |                  | Entanglement And Strangulation         | Consumers with infants who      |
|               |                      | MamaRoo      | ()               | Hazards                                | can crawl should immediately    |
|               |                      | Baby Swing,  |                  | 4moms Recalls More than 2 Million      | stop using the recalled swings  |
|               |                      | versions 1.0 |                  | MamaRoo and RockaRoo Infant            | and rockers, place them in an   |
|               |                      | through 4.0  |                  | Swings and Rockers Due to              | area where crawling infants     |
|               |                      | and          |                  | Entanglement and Strangulation         | cannot access and contact       |
|               |                      | RockaRoo     |                  | Hazards; One Death Reported            | 4moms immediately to register   |
|               |                      | Baby         |                  | When the swing or rocker is not in     | for a free strap fastener that  |
|               |                      | Rockers      |                  | use, their restraint straps can dangle | will prevent the straps from    |
|               |                      |              |                  | below the seat and non-occupant        | extending under the swing       |
|               |                      | (Country of  |                  | crawling infants can become            | when not in use.                |
|               |                      | Origin:      |                  | entangled in the straps, posing a      |                                 |
|               |                      | Unknown)     |                  | strangulation hazard.                  |                                 |
| 22-202        | USA                  | Hard Rock    |                  | Strangulation Hazard                   | Consumers should                |
|               |                      | Cafe         | MA 10 HOCK.      | Hard Rock Recalls Children's           | immediately take the recalled   |
|               |                      | Children's   |                  | Hooded Sweatshirts with                | sweatshirts away from a child   |
|               |                      | Hooded       |                  | Drawstrings Due to Strangulation       | and remove the drawstring to    |
|               |                      | Sweatshirts  |                  | Hazard                                 | eliminate the hazard or return  |
|               |                      |              |                  | The children's sweatshirts have a      | the sweatshirt to Hard Rock for |
|               |                      | (Country of  |                  | drawstring in the hood that can        | a full refund, shipping         |
|               |                      | Origin:      |                  | become entangled or caught on          | included.                       |
|               |                      | Portugal)    |                  | objects, posing a strangulation        |                                 |
|               |                      |              |                  | hazard to children.                    |                                 |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| 22 205 | USA | Kidoozic Mu                   |                                    | Entonglomont And Entropment Herende        | Concurrence should   |
|--------|-----|-------------------------------|------------------------------------|--|----------------------|
| 22-205 | USA | Kidoozie My<br>First Activity |                                    | Entanglement And Entrapment Hazards        | Consumers should     |
|        |     | -                             |                                    | Epoch Everlasting Play Recalls Kidoozie™   | immediately take     |
|        |     | Desk Toys                     | My First Activity Dask             | Activity Desk Toys Due to Entanglement     | the toys away from   |
|        |     |                               | Mon premier bureau d'activités 12. | and Entrapment Hazards                     | children, stop using |
|        |     | (Country of                   |                                    |  | them and contact     |
|        |     | Origin:                       |                                    | When attached to a crib, a protruding knob | Epoch Everlasting    |
|        |     | China)                        |                                    | on the activity desks can become entangled | Play for a free      |
|        |     |                               |                                    | with clothing on a child, posing an        | replacement or a     |
|        |     |                               |                                    | entanglement hazard. The opening in the    | full refund. The     |
|        |     |                               |                                    | handle on the desks can also pose a jaw    | company will         |
|        |     |                               |                                    | entrapment hazard to children under 18     | provide consumers    |
|        |     |                               |                                    | months.                                    | with a pre-paid      |
|        |     |                               |                                    |  | shipping label to    |
|        |     |                               |                                    |  | return the recalled  |
|        |     |                               |                                    |  | activity desk.       |
| 22-207 | USA | Big Game                      |                                    | Lead Toxicity                              | Consumers should     |
|        |     | Hunters                       |                                    | The brass water tap of the play kitchen    | immediately stop     |
|        |     | Children's                    |                                    | contains levels of lead that exceed the    | using the recalled   |
|        |     | Outdoor                       |                                    | federal lead content ban. Lead is toxic if | Big Game Hunters     |
|        |     | Kitchens                      | I                                  | ingested by young children and can cause   | Mud Kitchen,         |
|        |     | Recalled                      |                                    | adverse health issues.                     | remove and           |
|        |     | Due to                        |                                    |  | dispose of the brass |
|        |     | Violation of                  |                                    |  | water tap, and       |
|        |     | Federal                       |                                    |  | contact DOM          |
|        |     | Lead                          |                                    |  | Enterprises & Mfg.   |
|        |     | Content                       |                                    |  | Ltd. ("DOM Sports")  |
|        |     | Ban;                          |                                    |  | for a free           |
|        |     | Imported by                   |                                    |  | replacement water    |
|        |     | DOM                           |                                    |  | tap. Consumers will  |
|        |     | Sports; Sold                  |                                    |  | be contacted         |
|        |     | Exclusively                   |                                    |  | through Amazon's     |
|        |     | at                            |                                    |  | messaging            |
|        |     | Amazon.co                     |                                    |  | platform.            |
|        |     | m                             |                                    |  |                      |
|        |     |                               |                                    |  |                      |
|        |     | (Country of                   |                                    |  |                      |
|        |     | Origin:                       |                                    |  |                      |
|        |     | China)                        |                                    |  |                      |
|        |     | Giina)                        |                                    |  |                      |

| ESTC | NEWSLETTEF |
|------|------------|
|------|------------|

| 22-209 | USA  | Trek Model            |                                       | Fall And Crash Hazards                           | Consumers           |
|--------|------|-----------------------|---------------------------------------|--|---------------------|
|        | 00/1 | Year 2022             | Count-secret from (with secret second | Trek Bicycle Corporation Recalls Road            | should              |
|        |      | Speed                 | V V                                   | Bikes and Bicycle Handlebar/ Stems Due to        | immediately stop    |
|        |      | -                     | $\mathbf{r}$                          | Fall and Crash Hazards.                          |                     |
|        |      | Concept<br>SLR and MY |                                       | Fair and Clash Hazards.                          | using the recalled  |
|        |      |                       |                                       |  | bikes and           |
|        |      | 2021-2022             |                                       | The bicycle's carbon handlebars can crack,       | aftermarket         |
|        |      | Emonda                |                                       | posing fall and crash hazards.                   | handlebar/stems     |
|        |      | SLR                   |                                       |  | and contact their   |
|        |      | bicycles and          |                                       |  | local authorized    |
|        |      | MY                    |                                       |  | Trek retailer for a |
|        |      | 2020-2021-2           |                                       |  | free repair.        |
|        |      | 022                   |                                       |  |                     |
|        |      | aftermarket           |                                       |  |                     |
|        |      | Bontrager             |                                       |  |                     |
|        |      | Aeolus RSL            |                                       |  |                     |
|        |      | VR-C                  |                                       |  |                     |
|        |      | handlebar/st          |                                       |  |                     |
|        |      | ems                   |                                       |  |                     |
|        |      |                       |                                       |  |                     |
|        |      | (Country of           |                                       |  |                     |
|        |      | Origin:               |                                       |  |                     |
|        |      | China)                |                                       |  |                     |
| 22-211 | USA  | Blue's Clues          |                                       | Fall And Injury Hazards                          | Consumers           |
|        |      | Foot to               | 04                                    | Huffy Corporation Recalls Ride-On Toys           | should              |
|        |      | Floor                 |                                       | Due to Fall and Injury Hazards.                  | immediately take    |
|        |      | Ride-on               |                                       |  | the recalled        |
|        |      | Toys                  |                                       | The ride-on toy can tip forward when a           | ride-on toy away    |
|        |      |                       |                                       | young child is riding it, posing fall and injury | from children and   |
|        |      | (Country of           |                                       | hazards to children.                             | stop using it.      |
|        |      | Origin:               |                                       |  | Contact the firm    |
|        |      | China)                |                                       |  | for a free kit with |
|        |      |                       |                                       |  | instructions to     |
|        |      |                       |                                       |  | install a new stop  |
|        |      |                       |                                       |  | bar on the ride-on  |
|        |      |                       |                                       |  | toy.                |
|        | L    | 1                     |                                       | * Source:  | www.recalls.gov     |

### CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a "one stop shop" for U.S. Government recalls, <u>www.recalls.gov</u>, has been created. Publics can report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall program. Fast Track recalls are initiated by firms who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.

### **Recall Summary – Australia Toys / Children's Products**

NEWSLETTER

#### ACCC Recall List (Aug 2022)

| PRA No.        | Notifying<br>Country | Product  | Product<br>Photo | Hazard/ Risk   | Remedy  |
|----------------|----------------------|--|------------------|--|---|
| 2022/1955<br>9 | Australia            | Decathlon<br>(Australia) Pty<br>Ltd —<br>Snorkeling<br>inflatable wand<br>float - blue |                  | <b>Risk of Drowning</b><br>Users may not be aware of<br>important safety information about<br>the use of the product (example,<br>only use under supervision). There<br>is potentially an increased risk of<br>drowning if the product is not used<br>as intended. | Consumers should<br>immediately stop using<br>the product and return<br>the product to<br>Decathlon for a full<br>refund. |

### Australian Product Safety System

BSTC

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <u>https://www.productsafety.gov.au/recalls</u>.

NEWSLETTER

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and nearly 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but not limited to:

### **EU Requirements**

- EN 71
- Phthalates (EC) no. 1907/2006

ESTC

- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

#### **US & Canada Requirements**

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA Toys Regulations (SOR/2011-17)

#### **Japan Requirements**

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

#### **Australia Requirements**

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 DEHP

#### FOR MORE DETAILS, PLEASE CONTACT US:

| Hong Kong:         | hktcd@stc.group  | Dongguan | : 🧕 |
|--------------------|------------------|----------|-----|
| Changzhou:         | czstc@stc.group  | Vietnam: | vns |
| U.S.A.: <u>use</u> | nquiry@stc.group | Germany: | gr  |

ngguan: <u>dgtcd@stc.group</u> etnam: <u>vnstc@stc.group</u> rmany: <u>grstc@stc.group</u> Shanghai: <u>shtcd@stc.group</u> Japan: <u>jpo@stc.group</u>

