

## Recall Summary – European Toys

### EU Safety Gate Alerts (Jan 2023)

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A11/00017/23	Finland	<b>Toy blanket</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. Small parts (tail) can easily detach from the toy. A small child may put the stuffing material or the small part in the mouth and choke on it. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A12/00009/23	Sweden	<b>Children´s high chair</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The construction allows the seat of the high chair to slide away and come off. A child can fall out of the chair, resulting in injuries. The product does not comply with the requirements of the General Product Safety Directive.	Recall of the product from end users
A12/00010/23	Italy	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b> The plastic material of the product contains an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 54.26 % by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive systems. The product does not comply with the REACH Regulation.	Ban on the marketing of the product and any accompanying measures
A12/00011/23	Poland	<b>Set of plastic toys</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy contains an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 0.57% and 3.19% by weight, respectively). These phthalates may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Warning consumers of the risks

A12/00012/23	Poland	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts (pacifier and bottle holders) may easily detach from the toy. Moreover, the plastic bottle may easily break, generating small parts. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/00013/23	Poland	<b>Plastic ball</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy contains an excessive amount of Diisobutyl Phthalate (DIBP) (measured value up to: 36%). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Warning consumers of the risks
A12/00015/23	Poland	<b>Puzzle play mat</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The mat has small parts which may easily detach. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/00016/23	Poland	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts (wheel, wheel with axle and plastic handle) may easily detach from the toy. A child may put the small parts in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the relevant European standard EN 71-1.	Warning consumers of the risks
A12/00018/23	Finland	<b>Head band with LED lights</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The battery compartment is easily opened, leaving the button batteries accessible. A child could put them in the mouth, which could cause damage to the children's gastrointestinal tract if swallowed. The product does not comply with the requirements of the Toy Safety Directive nor with the relevant European standard EN 62115.	Withdrawal of the product from the market

A12/00023/23	Czechia	<b>Battery operated toy</b>  (Country of Origin: <b>China</b> )		<b>Environment</b>  The solder joint has an excessive concentration of lead (measured value up to 46.7% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/00025/23	Poland	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  Small part (the eye) may easily detach from the toy. A small child may put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/00026/23	Poland	<b>Squeezable toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  A small part (the eye) may easily detach from the toy. A small child may put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
A12/00028/23	Czechia	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The plastic material of the head and hands of the doll contains di-(2-ethylhexyl) phthalate (DEHP) (measured values up to 21.32% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive systems. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market

A12/00029/23	Czechia	<b>Plastic doll set</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the head of the doll contains di-(2-ethylhexyl) phthalate (DEHP) (measured values: 26.3% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive systems. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/00032/23	Ireland	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy releases an excessive amount of bisphenol A (measured value: 0.1 mg/l). Bisphenol A has endocrine disrupting properties and affects the mammary glands, reproductive and immune systems and may impair the brain's development and the create adverse behavioral outcomes in children. The product does not comply with the requirements of the Toy Safety Directive.	Recall of the product from end users
A12/00040/23	Austria	<b>Soft toy</b>  (Country of Origin: <b>Czechia</b> )		<b>Choking</b> A small part (nose) can easily detach. A small child may put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/00045/23	Germany	<b>Squeeze toy</b>  (Country of Origin: <b>Unknown</b> )		<b>Microbiological</b> The liquid in the product is contaminated with aerobic mesophilic bacteria, mostly Burkholderia Gladioli (measured value 600000 CFU/g). If the product is damaged fluid may leak out, infecting the user particularly in case of skin injuries. Burkholderia Gladioli may cause infections such as pneumonia, wound infections and sepsis, especially in immunocompromised people. The product does not comply with the requirements of the Toy Safety Directive.	Withdrawal of the product from the market

A12/00058/23	Luxembourg	<b>Magnetic balls</b>  (Country of Origin: <b>Unknown</b> )		<b>Injuries</b>  The toy is made of small parts (balls) with a high magnetic flux. If a child swallows them, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A12/00063/23	Italy	<b>Multifunctional toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP)(measured values up to 0.03% and 0.5% by weight, respectively). These phthalates may harm the health of children, possibly causing damage to their reproductive systems. The product does not comply with the REACH Regulation.	Ban on the marketing of the product and any accompanying measures
A12/00064/23	Italy	<b>Slime toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The migration of boron from the slime is too high (measured value up to 2331 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Ban on the marketing of the product and any accompanying measures
A12/00079/23	Poland	<b>Pram mobile</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  The bell and all the pieces of the pram mobile can be easily detached and break, releasing small parts (rattling elements or other small pieces). A child may put the small parts in the mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Destruction of the product

A12/00107/23	Czechia	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 33,8% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive systems. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/00123/23	Italy	<b>Modelling clay</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The migration of boron from the toy slime is too high (measured values up to 1940 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Ban on the marketing of the product and any accompanying measures
A12/00128/23	Germany	<b>Baby carrier</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b>  Due to insufficient attachment options on the baby carrier, proper support is not ensured and a baby may slip out of the carrier, fall and suffer fatal injuries. The product does not comply with the requirements of General Product Safety Directive nor with the European standard EN 13209-2.	Removal of this product listing by the online marketplace
A12/00129/23	Germany	<b>Baby carrier</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b>  Due to insufficient attachment options on the baby carrier, the support may be inadequate and the baby can slip out of the carrier, fall and suffer fatal injuries. The product does not comply with the requirements of General Product Safety Directive nor with the European standard EN 13209-2.	Recall of the product from end users

A12/00130/23	Germany	<b>Jumping ball</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the product contains an excessive concentration of Diisobutyl Phthalate (DIBP) (measured values: up to 19.84% by weight). This phthalate may harm the health, possibly causing damage to the reproductive system. The product does not comply with the REACH Regulation.	Warning consumers of the risks
A12/00131/23	Iceland	<b>Toy train</b>  (Country of Origin: <b>Belgium</b> )		<b>Choking</b> Small parts can easily detach (pins of train). A small child may put them in the mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
A12/00134/23	Poland	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy contains an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 5.6% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Destruction of the product
A12/00144/23	Italy	<b>Multifunctional toy</b>  (Country of Origin: <b>Hong Kong</b> )		<b>Chemical, Choking, Hearing Damage</b> The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP)(measured values up to 3.08% and 2.59% by weight, respectively). These phthalates may harm the health of children, possibly causing damage to their reproductive systems. The toy releases small parts which a child may put in the mouth and choke on. Finally, the sound pressure level is too high (measured value up to: 82.4 dB) which can lead to temporary or permanent loss of hearing. The product does not comply with the REACH Regulation nor with the requirements of the Toy Safety Directive nor with the standard EN 71-1.	Ban on the marketing of the product and any accompanying measures

A12/00145/23	Czechia	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The plastic material of the head of the doll contains di-(2-ethylhexyl) phthalate (DEHP) (measured values: 31.7% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive systems. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/00146/23	Germany	<b>Baby carrier</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b>  Due to insufficient attachment options, the baby carrier cannot ensure adequate support. A baby may slip out of the carrier, fall and be fatally injured. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 13209-2.	Recall of the product from end users
A12/00151/23	Poland	<b>Inflatable ball</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The toy contains an excessive amount of Diisobutyl Phthalate (DIBP) (measured value up to: 25.3%). This phthalate may harm the health of children, possibly causing damage to their reproductive systems. The product does not comply with the REACH Regulation.	Destruction of the product
A12/00153/23	Poland	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  The toy can break easily and release small parts from the smaller figurine. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
A12/00158/23	Lithuania	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  Small parts (headband, necklace, shoulder bag) can easily detach. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market

A12/00159/23	Lithuania	<b>Toy puppy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts may easily detach from the toy. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/00161/23	Germany	<b>Fancy-dress mask</b>  (Country of Origin: <b>China</b> )		<b>Burns</b> The material of the mask is easily flammable and the flame propagation is too high. If it catches fire, the user could suffer burns. The product does not comply with the requirements of the Toy Safety Directive and EN 71-2.	Withdrawal of the product from the market
A12/00163/23	Hungary	<b>Toy telephone</b>  (Country of Origin: <b>China</b> )		<b>Damage to hearing</b> The sound pressure level produced by the toy is too high (measured values: up to 81.1 dB), which could lead to permanent or partial hearing loss. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/00174/23	Poland	<b>Inflatable ball</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy contains an excessive concentration of Diisobutyl Phthalate (DIBP) (measured value up to: 31.2%). This phthalate may harm the health of children, possibly causing damage to their reproductive systems. The product does not comply with the REACH Regulation.	Warning consumers of the risks
A12/00179/23	Germany	<b>Baby carrier</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> Due to the insufficient attachment options on the baby carrier, the support is inadequate and the baby may slip out of the carrier. The baby may fall and suffer injuries. The product does not comply with the requirements of General Product Safety Directive nor with the European standard EN 13209-2.	Recall of the product from end users

A12/00180/23	Germany	<b>Baby carrier</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> Due to the insufficient attachment options on the baby carrier, the support is inadequate and the baby may slip out of the carrier. The baby may fall and suffer injuries. The product does not comply with the requirements of General Product Safety Directive nor with the European standard EN 13209-2.	Recall of the product from end users
A12/00181/23	Germany	<b>Baby carrier</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> Due to the insufficient attachment options on the baby carrier, the support is inadequate and the baby may slip out of the carrier. The baby may fall and suffer injuries. The product does not comply with the requirements of General Product Safety Directive nor with the European standard EN 13209-2.	Recall of the product from end users

## Safety Gate: the EU rapid alert system for dangerous non-food products

“Safety Gate”, the EU rapid alert system (formerly known as ‘RAPEX’), enables the rapid exchange of information between **31 European countries** and the European Commission on non- food dangerous products found on the market posing a risk to health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on <https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports>. The measures taken in the notifying country in order to restrict their marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (**2001/95/EC**) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

## Recall Summary – US Toys / Children’s Products

**CPSC Recall List (Jan 2023)**

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
23-085	USA	<b>Children’s pajamas</b>  (Country of Origin: <b>China</b> )		<b>Burn Hazard</b> P.J. Salvage Recalls Children’s Pajamas Due to Burn Hazard  The recalled children’s pajamas fail to meet the federal flammability standards for the children’s sleepwear, posing a risk of burn injuries to the children.	Consumers should immediately take the recalled pajamas away from the children, stop using them and contact P.J. Salvage for instructions on how to receive a pre-paid mailer and return the pajamas for a full refund. Consumers who purchased the pajamas directly from P.J. Salvage will be contacted via email and/or postage mail.
23-088	USA	<b>All models of Rock ‘n Play Sleepers</b>  (Country of Origin: <b>China</b> )		<b>Fatalities</b> Fisher-Price Reannounces Recall of 4.7 Million Rock ‘n Play Sleepers; At Least Eight Deaths Occurred After Recall  Infant fatalities have occurred in the Rock ‘n Play Sleepers, after the infants rolled from their back to their stomach or side while unrestrained, or under other circumstances.	Consumers should stop using the Rock ‘n Play immediately and contact Fisher-Price for a refund or voucher. It is illegal to sell or distribute the recalled sleepers.
23-089	USA	<b>All models of Kids2 Rocking Sleepers</b>  (Country of Origin: <b>China</b> )		<b>Fatalities</b> Kids2 Reannounces Recall of 694,000 Rocking Sleepers; Four Additional Deaths After Recall  Infant fatalities have occurred in the Rocking Sleepers, after the infants rolled from their back to their stomach or side while unrestrained, or under other circumstances.	Consumers should stop using the rocking sleeper immediately and contact Kids2 for a refund. It is illegal to sell or distribute the recalled sleepers.

23-095	USA	<p><b>Children's robes</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Burn Hazard</b></p> <p>Vaenait Baby Recalls Children's Robes Due to Violation of Federal Flammability Standards and Burn Hazard</p> <p>The children's robes fail to meet the federal flammability standards for the children's sleepwear, posing a risk of burn injuries to the children.</p>	<p>Consumers should immediately take the recalled robes away from the children, stop using them and contact Vaenait Baby for a full refund. Consumers who purchased the robes will be asked to destroy the robes by cutting them in half and send the recalling firm a photo of the destroyed garment. Upon receipt of the photo, consumers will be issued a full refund of the purchase price.</p>
23-097	USA	<p><b>Children's Pajama Sets</b></p> <p>(Country of Origin: <b>United Kingdom and Bangladesh</b>)</p>		<p><b>Burn Hazard</b></p> <p>Children's Pajama Sets Recalled Due to Violation of Federal Flammability Standards and Burn Hazard; Manufactured by Selfie Craft Company</p> <p>The children's pajama sets fail to meet flammability standards for children's sleepwear, posing a risk of burn injuries to the children.</p>	<p>Consumers should immediately take the recalled pajama sets away from the children, stop using them and contact the Selfie Craft Company. Consumers are to destroy the recalled pajama sets by cutting them in half vertically and submitting a photo of the destroyed pajama set to Selfie Craft Company for a full refund. Selfie Craft Company is contacting all known purchasers directly.</p>
23-099	USA	<p><b>Children's sleepwear</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Burn Hazard</b></p> <p>NewCosplay Children's Sleepwear Recalled Due to Violation of Federal Flammability Standards and Burn Hazard; Imported by Mianzhu Ye Xin Trading; Sold Exclusively at Amazon.com</p> <p>The recalled children's sleepwear fails to meet the federal flammability standards for children's sleepwear, posing a risk of burn injuries to the children.</p>	<p>Consumers should immediately take the recalled sleepwear garments away from children, stop using them and contact Mianzhu Ye Xin Trading for a full refund. Consumers should destroy the garments by cutting them in half and email Mianzhu Ye Xin Trading a photo of the destroyed garment at lingbahao08@163.com.</p>

23-100	USA	<p><b>Children's sleepwear</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Burn Hazard</b></p> <p>NewCosplay Children's Sleepwear Recalled Due to Violation of Federal Flammability Standards and Burn Hazard; Imported by Weihai Juanhai Decoration Material; Sold Exclusively at Amazon.com</p> <p>The recalled children's sleepwear fails to meet the federal flammability standards for children's sleepwear, posing a risk of burn injuries to the children.</p>	<p>Consumers should immediately take the recalled sleepwear garments away from the children, stop using them and contact Weihai Juanhai Decoration Material for a full refund. Consumers should destroy the garments by cutting them in half and email Weihai Juanhai Decoration Material a photo of the destroyed garment at <a href="mailto:suzhoudt123@163.com">suzhoudt123@163.com</a></p>
23-101	USA	<p><b>Children's sleepwear</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Burn Hazard</b></p> <p>NewCosplay Children's Sleepwear Recalled Due to Violation of Federal Flammability Standards and Burn Hazard; Imported by Hainan Chong Yu Industrial; Sold Exclusively at Amazon.com</p> <p>The recalled children's sleepwear fails to meet the federal flammability standards for children's sleepwear, posing a risk of burn injuries to the children.</p>	<p>Consumers should immediately take the recalled sleepwear garments away from the children, stop using them and contact Hainan Chong Yu Industrial for a full refund. Consumers should destroy the garments by cutting them in half and email Hainan Chong Yu Industrial a photo of the destroyed garment at <a href="mailto:lingershierhao22@163.com">lingershierhao22@163.com</a>. Upon receipt of the photo, consumers will be issued a full refund of the purchase price. Hainan Chong Yu Industrial and Amazon are contacting all known purchasers directly.</p>

23-102	USA	<p><b>Children's sleepwear</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Burn Hazard</b></p> <p>NewCosplay Children's Sleepwear Recalled Due to Violation of Federal Flammability Standards and Burn Hazard; Imported by Shanghai Jing Cheng Landscape Engineering Company; Sold Exclusively at Amazon.com</p> <p>The recalled children's sleepwear fails to meet the federal flammability standards for children's sleepwear, posing a risk of burn injuries to the children.</p>	<p>Consumers should immediately take the recalled sleepwear garments away from the children, stop using them and contact Shanghai Jing Cheng Landscape Engineering Company for a full refund. Consumers should destroy the garments by cutting them in half and email Shanghai Jing Cheng Landscape Engineering Company a photo of the destroyed garment at 591025473@qq.com. Upon receipt of the photo, consumers will be issued a full refund of the purchase price.</p>
23-103	USA	<p><b>Children's sleepwear</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Burn Hazard</b></p> <p>NewCosplay Children's Sleepwear Recalled Due to Violation of Federal Flammability Standards and Burn Hazard; Imported by Shanghai Jinhui Gardening Center; Sold Exclusively at Amazon.com</p> <p>The recalled children's sleepwear fails to meet the federal flammability standards for children's sleepwear, posing a risk of burn injuries to the children.</p>	<p>Consumers should immediately take the recalled sleepwear garments away from the children, stop using them and contact Shanghai Jinhui Gardening Center for a full refund. Consumers should destroy the garments by cutting them in half and email Shanghai Jinhui Gardening Center a photo of the destroyed garment at ttdd024@163.com. Upon receipt of the photo, consumers will be issued a full refund of the purchase price. Shanghai Jinhui Gardening Center and Amazon are contacting all known purchasers directly.</p>

23-104	USA	<p><b>Children's sleepwear</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Burn Hazard</b></p> <p>NewCosplay Children's Sleepwear Recalled Due to Violation of Federal Flammability Standards and Burn Hazard; Imported by Shanghai Xunao Elevator; Sold Exclusively at Amazon.com</p> <p>The recalled children's sleepwear fails to meet the federal flammability standards for children's sleepwear, posing a risk of burn injuries to the children.</p>	<p>Consumers should immediately take the recalled sleepwear garments away from the children, stop using them and contact Shanghai Xunao Elevator for a full refund. Consumers should destroy the garments by cutting them in half and email Shanghai Xunao Elevator a photo of the destroyed garment at chenye1964@163.com. Upon receipt of the photo, consumers will be issued a full refund of the purchase price. Shanghai Xunao Elevator and Amazon are contacting all known purchasers.</p>
23-106	USA	<p><b>Children's Lounge Pants</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Burn Hazard</b></p> <p>Properly Tied Recalls Children's Lounge Pants Due to Violation of Federal Flammability Standards and Burn Hazard</p> <p>The recalled children's sleepwear fails to meet the federal flammability standards for children's sleepwear, posing a risk of burn injuries to the children.</p>	<p>Consumers should immediately take the recalled children's sleepwear away from the children, stop using them and contact Properly Tied for instructions on how to receive a pre-paid mailer to return the lounge pants for a full refund. Properly Tied is contacting all known purchasers.</p>

\* Source: [www.recalls.gov](http://www.recalls.gov)

## CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a "one stop shop" for U.S. Government recalls, <http://www.recalls.gov>, has been created. Publics can report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall program. Fast Track recalls are initiated by firms who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.

## Recall Summary – Australia Toys / Children’s Products

**ACCC Recall List (Jan 2023)**

PRA No.	Notifying Country	Product/ Description	Product Photo	Hazard/ Risk	Remedy
2022/19669	Australia	<p><b>Various lithium button batteries.</b></p> <p><b>Batteries were sold in packs containing up to 5 batteries.</b></p> <p><b>CR2016</b> <b>CR2025</b> <b>CR2430</b> <b>CR2450</b> <b>CR2032</b></p>		<p><b>Missing of Warnings</b></p> <p>The button battery packaging does not have the correct warning symbols and wording.</p> <p>If the young children gain access to button batteries and ingest them, they are likely to suffer severe internal burn injuries, which can result in serious injury or death. Button batteries also pose a choking hazard to the young children.</p>	<p>Consumers should keep the batteries out of reach of children.</p> <p>Consumers can contact FITN Trading and Service Pty Ltd by emailing <a href="mailto:huwising@gmail.com">huwising@gmail.com</a> or calling 0451866580 to arrange a refund.</p>
2022/19676	Australia	<p><b>For Baby and Up - Green Sprouts Stainless-steel Sippy Cup - 6oz</b></p>		<p><b>Poisoning Risk</b></p> <p>The base of the bottle could break off exposing a solder dot that contains lead.</p> <p>Lead poses a poisoning risk to the children. If lead is ingested by the young children, it can cause adverse health effects.</p>	<p>Consumers should stop using the product immediately and contact For Baby and Up for a full refund, including shipping.</p>
2022/19679	Australia	<p><b>Grey baby sleep sack with a small, weighted, cloud-shaped patch on the front. The product comes in multiple sizes to suit different ages.</b></p>		<p><b>Risk Of Suffocation</b></p> <p>The sleep sack contains a weighted patch that poses compression or suffocation risk. Safe infant sleeping guidance discourages use of weighted swaddles and sleepwear. Weighted sleepwear can restrict an infant’s chest and abdominal movement which increases the risk of suffocation.</p> <p>Weighted products can also limit an infant’s movements. For example, if an infant rolled onto its stomach it may not be able to roll back over.</p>	<p>Consumers should stop using the product immediately and contact Bubpods to arrange to return the product for a full refund.</p>

2023/19696	Australia	<b>Dimmeys - Babe Rattle 4 Piece and 7 Piece Set</b>		<p><b>Choking Or Suffocation Hazard</b></p> <p>The rattle does not comply with the size and shape requirements of the mandatory safety standard for toys for the children up to and including 36 months of age.</p> <p>The rattle may pose a choking or suffocation hazard for the young children, which can lead to severe injury or death.</p>	<p>Consumers should immediately stop using the rattle set, destroy the product, and contact Dimmeys to arrange a full refund.</p>
2023/19697	Australia	<b>Wooden rattles sold in various 3, 4 and 5 piece personalized baby gift sets. Gift sets include a combination of products such as rattles, combs, hair brushes, forks and spoons.</b>		<p><b>Choking Or Suffocation Hazard</b></p> <p>The rattles do not comply with the size and shape requirements of the mandatory safety standard for toys for the children up to and including 36 months of age.</p> <p>The rattle may pose a choking or suffocation hazard for the young children, which can lead to severe injury or death.</p>	<p>Consumers should immediately stop using the rattle.</p>

## Australian Product Safety System

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <https://www.productsafety.gov.au/recalls>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but not limited to:

### EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

### US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

### Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

### Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

#### FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: [hktcd@stc.group](mailto:hktcd@stc.group)

Changzhou: [czstc@stc.group](mailto:czstc@stc.group)

U.S.A.: [usenquiry@stc.group](mailto:usenquiry@stc.group)

Dongguan: [dgtcd@stc.group](mailto:dgtcd@stc.group)

Vietnam: [vnstc@stc.group](mailto:vnstc@stc.group)

Germany: [grstc@stc.group](mailto:grstc@stc.group)

Shanghai: [shtcd@stc.group](mailto:shtcd@stc.group)

Japan: [jpo@stc.group](mailto:jpo@stc.group)

