

Recall Summary - European Toys / Children's Products

EU Safety Gate Alerts (Sep 2025)

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
OR/00140/25 OR/00141/25	France	Keyring (Country of Origin: China) Soft toy (Country of Origin: China)	PHOTO STATE OF THE PHOTO STATE O	Choking The fibrous stuffing material of the toy is easily accessible. A small child could put stuffing material in mouth and choke The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-1. Choking The fibrous stuffing material of the toy is easily accessible. A small child could put stuffing material in mouth and choke. The product does not comply with the requirements of the Toy Safety Directive, nor with the European	Withdrawal of the product from the market Recall of the product from end users
OR/00143/25	France	Soft toy (Country of Origin: China)		standard EN 71-1. Choking The fibrous material of the toy (fur) is easily accessible. A small child could put this material in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-1.	Recall of the product from end users
OR/00144/25	Hungary	Soft toy (Country of Origin: China)		Choking The fibrous stuffing material of the toy is easily accessible due to the weakness of the seams. A small child may put the filling material in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
OR/00146/25	France	Soft toy (Country of Origin: China)		Choking The fibrous stuffing material of the toy is easily accessible. A small child could put stuffing material in the mouth and choke. The product does not comply with the requirements of the	Recall of the product from end users





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				Toy Safety Directive, nor with the European	
				standard EN 71-1.	
OR/00147/25	France	Soft toy		Choking	Recall of the
				The fibrous stuffing material of the toy is easily	product from
		(Country of		accessible. A small child could put stuffing	end users
		Origin:		material in their mouth and choke. The	
		China)		product does not comply with the	
				requirements of the Toy Safety Directive, nor	
				with the European standard EN 71-1.	
SR/03122/25	Sweden	Soft toy		Environment	Withdrawal of
				The solders in the product have an excessive	the product
		(Country of	12000045245756022	concentration of lead and cadmium (measured	from the
		Origin:	The Page (Section Deal Section) has a locating deal place of the page (Section Deal Section Deal Deal Section Deal Section Deal Section Deal Section Deal Section	values up to 83.5% and 0.36% by weight,	market
		China)		respectively). Lead and cadmium pose a risk	
				to the environment. The product does not	
				comply with the requirements of the Directive	
				on the restriction of the use of certain	
				hazardous substances in electrical and	
				electronic equipment (RoHS 2 Directive).	
SR/03128/25	Germany	Soft toy		Choking	Removal of
				The toy has small parts (eyes and nose) that	this product
		(Country of		can be easily detached. A small child could	listing by the
		Origin:	all	put them in the mouth and choke. The product	online
		China)		does not comply with the requirements of the	marketplace
				Toy Safety Directive nor with the European	
				standard EN 71-1.	
SR/03133/25	Poland	Plastic toy		Choking, Damage to Sight, Injuries	Withdrawal of
		set		The suction cup of the projectiles can easily	the product
				detach. A child may put them in the mouth and	from the
		(Country of		choke. In addition, a projectile can hit a child's	market
		Origin:		eye causing injuries and damage to sight. The	
		China)		product does not comply with the	
				requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	



Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03137/25	Czechia	Plastic doll	2 3 3	Chemical	Destruction of
				The plastic material of the doll has an	the product
		(Country of	5 a a	excessive concentration of bis(2-ethylhexyl)	
		Origin:	Dr. G. Drives	phthalate (DEHP) and dibutyl phthalate (DBP)	
		China)		(measured values 4.51% and 0.47% by	
				weight, respectively). These phthalates may	
				harm the health of children by causing	
				possible damage to their reproductive system.	
				The product does not comply with the REACH	
OD /004 40/05	Deleval	Fabric (a)		Regulation.	NA - Line or Ale -
SR/03140/25	Poland	Fabric toy	Miękka ksiądeczka	Choking	Making the
		book		The product has a protruding part (red plastic	marketing of
		(Country of		attachment handle). A child could put it into	the product
		(Country of		the mouth and choke. The product does not	subject to prior conditions
		Origin:		comply with the requirements of the Toy	Conditions
		China)		Safety Directive nor with the European standard EN 71-1.	
OD /004 44 /05	Deleval	T			\\\\ i
SR/03141/25	Poland	Toy gun set	2 409	Choking	Warning
		(Country of		Small parts (foam projectiles) can easily	consumers of the risks
		(Country of	Basaveri	detach. A small child may put them in the	the risks
		Origin:		mouth and choke. The product does not	
		China)		comply with the requirements of the Toy	
				Safety Directive nor with the European	
OD/00454/05	O d a	Obildes		standard EN 71-1.	Damassalaf
SR/03154/25	Sweden	Children	3-	Environment	Removal of
		digital		The solders in the product have an excessive	this product
		camera		concentration of lead (measured value up to	listing by the online
		(Country of		76% by weight). Lead poses a risk to the	
		(Country of		environment. The product does not comply	marketplace
		Origin:		with the requirements of the Directive on the	
		China)		restriction of the use of certain hazardous	
				substances in electrical and electronic	
CD/00450/05	Dolored	Triovala		equipment (RoHS 2 Directive).	Impropried a second
SR/03158/25	Poland	Tricycle		Entrapment, Injuries	Import rejected
		(Country of		The mechanical strength of the tricycle is	at border
		(Country of	Y	inadequate and it may dismantle during use,	
		Origin:		leading to injuries. There are accessible gaps	
		China)		between moving parts of the tricycle. A child's	
				leg may become trapped there and be injured.	3





Alert No.	Notifying	Product	Product	Hazard/ Risk	Measures
Alert NO.	Country	Froduct	Photo	Hazaru/ Kisk	Adopted
				The product does not comply with the	
				requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/03160/25	Poland	Soft toy		Choking	Import rejected
			District and little	The toy has small parts (plastic strings	at border
		(Country of	The state of the s	connecting the hat to the animal's head) which	
		Origin:	Mark S. Comment of the Comment of th	can easily detach. A small child may put them	
		China)		in the mouth and choke. The product does not	
				comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71-1.	
SR/03162/25	Poland	Baby		Choking	Import rejected
		teether	9,07	A small part (plastic ball with attached cord)	at border
				can easily detach. A child may put them in	
		(Country of		their mouth and choke. The product does not	
		Origin:		comply with the requirements of the Toy	
		China)		Safety Directive nor with the European	
				standard EN 71-1.	
SR/03165/25	Poland	Plastic toy		Choking	Import rejected
				Small parts (plastic wings) can easily detach.	at border
		(Country of		A child may put them in their mouth and	
		Origin:		choke. The product does not comply with the	
		China)		requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/03166/25	Germany	Soft toy		Choking	Stop of sales
			0	The toy has small parts that can be easily	
		(Country of		detached (eyes). As a result, a small child	
		Origin:		could put them in the mouth and choke. The	
		China)		product does not comply with the	
				requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/03184/25	Poland	Soft toy		Choking, Strangulation	Import rejected
				The electrical cables are easily accessible	at border
		(Country of		because the compartment is only protected	
		Origin:		with a velcro fastener. These cables may form	
		China)		a loop large enough for a small child to wrap	
				the wires around its neck, which may lead to	
				strangulation. Additionally, the fibrous stuffing	





NEWSLETTER

Issue no.: 40/25/TCD

Alert No.	Notifying	Product	Product	Hazard/ Risk	Measures
Alort No.	Country	Troduct	Photo	Tidzaid/ Niok	Adopted
				material of the toy is also easily accessible for	
				the same reason. A small child could put	
				stuffing material in the mouth and choke. The	
				product does not comply with the	
				requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/03187/25	Poland	Plastic		"Choking	Import rejected
		interactive		The product has small parts (plastic "ears"	at border
		toy		made of rubber-like material) which can easily	
			A Designation	detach. A child may put these in the mouth	
		(Country of	新加州 一	and choke. The product does not comply with	
		Origin:		the requirements of the Toy Safety Directive	
		China)		nor with the European standard EN 71-1."	
SR/03208/25	Hungary	Toy doll set		Chemical	Withdrawal of
			Pre 1 42 0 40	The product has an excessive concentration	the product
		(Country of		of bis(2-ethylhexyl) phthalate (DEHP) and	from the
		Origin:	THE MANAGEMENT OF	dibutyl phthalate (DBP) (measured values:	market
		China)		31% and 0.18% by weight, respectively).	
				These phthalates may harm the health of	
				children, causing possible damage to their	
				reproductive system. The product does not	
				comply with the REACH Regulation.	
SR/03210/25	Hungary	Bath toy		Chemical, Choking	Withdrawal of
				The product has an excessive concentration	the product
		(Country of	0° 1° 5	of bis(2-ethylhexyl) phthalate (DEHP)	from the
		Origin:		(measured value: 30% by weight). This	market
		China)		phthalate may harm the health of children,	
				causing possible damage to their reproductive	
				system. In addition, small plastic parts	
				(squeaking element) may easily detach from	
				the toy. A small child may put them in the	
				mouth and choke. The product does not	
				comply with the requirements of the Toy	
				Safety Directive and the REACH Regulation	
				nor with the European standard EN 71-1.	





Alout No.	Notifying	Droduct	Product	Howard/ Bigh	Measures
Alert No.	Country	Product	Photo	Hazard/ Risk	Adopted
SR/03225/25	Poland	Toy whistle		Choking, Damage to hearing	Withdrawal of
		set		The whistle is a small part. A small child may	the product
			AP DO	put it in the mouth and choke. Moreover, the	from the
		(Country of		sound pressure level produced by the toy is	market
		Origin:		too high (measured value up to 118.9 dB).	
		China)		This could lead to permanent or partial	
				hearing loss. The product does not comply	
				with the requirements of the Toy Safety	
				Directive nor with the European standard EN	
				71-1.	
SR/03228/25	Sweden	Cradle		Entrapment, Suffocation	Recall of the
				The cradle's swinging motion is excessive,	product from
		(Country of	AND COLUMN TO SERVICE AND ADDRESS OF THE PARTY OF THE PAR	which can cause a child to roll over and	end users
		Origin:		become unable to return to a supine position,	
		China)		potentially leading to suffocation. Additionally,	
				the distance between the frame and body of	
				the crib is too small, posing a risk of finger	
				entrapment. The product does not comply with	
				the General Product Safety Regulation nor	
				with the European standard EN 1130.	
SR/03229/25	France	Toy chef's	100	Burns	Recall of the
		hat	EAPPétit	The toy hat is highly inflammable and the	product from
			L'ASS	flame propagation is too high. It may catch fire	end users
		(Country of	Depart Br	if worn close to an ignition source, resulting in	
		Origin:		burns. The product does not comply with the	
		Vietnam)		requirements of the Toy Safety Directive nor	
				with the European standard EN 71-2.	
SR/03241/25	Sweden	Cradle		Asphyxiation, Entrapment, Suffocation	Recall of the
				The cradle exceeds the maximum permissible	product from
		(Country of	MILL.	tilt angle/sideway angle. If a child rolls over, it	end users
		Origin:		can be unable to return to a supine position	
		Unknown)		and its nose and mouth can be obstructed,	
				causing suffocation. If the pressure is on its	
				chest, there is also a risk of asphyxiation.	
				Moreover, the distance between the crib and	
				the frame is too small, which could lead to the	
				child having a finger entrapped between them.	
				Additionally, the wheels can easily unlock,	
				which could lead to unintended move of the	





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				crib, which could cause that the child has its	
				limbs entrapped in it. The product does not	
				comply with the General Product Safety	
				Regulation nor with the European standard	
				EN 1130.	
SR/03243/25	Poland	Soft toy		Choking	Import rejected
				Small parts (metal ring and right hand) can	at border
		(Country of	POP MASI	easily detach. As a result, a small child could	
		Origin:		put them in the mouth and choke. The product	
		China)	and the	does not comply with the requirements of the	
				Toy Safety Directive nor with the European	
				standard EN 71-1.	
SR/03247/25	Poland	Soft toy		Choking	Recall of the
				The toy has small parts (plastic eyes) that can	product from
		(Country of	E	be easily detach. A small child may put them	end users
		Origin: Peru)		into the mouth and choke. The product does	
				not comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71-1.	
SR/03255/25	France	Musical toy		Choking	Recall of the
			Ju Both o Phagus Danong	The toy contains small parts that can easily	product from
		(Country of	1	detach (the hen figurine). Small children may	end users
		Origin: Hong	Specification of Specif	put them in their mouth and choke. The	
		Kong)		product does not comply with the	
				requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/03264/25	UK	Baby walker		Choking	Destruction of
				The product has small parts (metal bell) that	the product
		(Country of		can easily detach. A small child may put them	
		Origin:		in the mouth and choke. The product does not	
		China)		comply with the requirements of the Toy	
				Safety Directive.	
SR/03265/25	UK	Sensory toy		Strangulation	Removal of
		set		The wooden rainbow ring component of the	this product
				toy set features a long ribbon. This ribbon can	listing by the
		(Country of	are and a second a	become wrapped around a baby's neck during	online
		Origin: UK)		various activities, leading to strangulation. The	marketplace





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				product does not comply with the	
				requirements of the Toy Safety Directive.	
SR/03276/25	UK	Children's mask (Country of Origin: China)		Injuries The product has an eye shield which can easily detach. Once the shield is detached, two protruding posts and screws are present at or very close to the user's eye level. These screws could contact the eyes or soft skin area during use, causing injuries to the user. The product does not comply with the	Import rejected at border
				requirements of the Toy Safety Directive.	
SR/03286/25	Lithuania	Soft toy (Country of Origin: Peru) Soft toy (Country of Origin: China)		Choking The product has small parts (plastic eyes) that can easily detach. Small children may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive. Strangulation The product has long functional cords with free ends. These cords can become trapped during various activities of a child, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN	Recall of the product from end users Withdrawal of the product from the market
SR/03288/25 SR/03289/25	Spain	Playmat (Country of Origin: China)	12-3 Duzile 13 Crounal 13	71-1. Choking The tiles of the toy can easily break and form small parts. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. Choking	Ban on the marketing of the product and any accompanying measures
		(Country of Origin: China)		The product has small parts (foam arch ends and assembly screws) that can easily detach. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive.	at border





NEWSLETTER

Issue no.: 40/25/TCD

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03308/25	Ireland	Radio-		Cuts	Removal of
		controlled		The product contains sharp edges and parts	this product
		toy car		that may be accessible to the user, creating a	listing by the
				risk of cuts. The product does not comply with	online
		(Country of		the requirements of the Toy Safety Directive.	marketplace
		Origin:			
		Unknown)			
SR/03317/25	France	Children's		Choking	Withdrawal of
		sandals		Small parts can easily detach (sandal	the product
				buttons). As a result, a small child may put	from the
		(Country of		them in the mouth and choke. The product	market
		Origin:		does not comply with the requirements of the	
		China)		Toy Safety Directive, nor with the European	
				standard EN 71-1.	
SR/03320/25	Hungary	Toy rattle	() () () () () () () () () ()	Choking	Withdrawal of
		set		The product has small parts (balls and	the product
				monkey's face) that can easily detach. A small	from the
		(Country of		child may put them in their mouth and choke.	market
		Origin:		The product does not comply with the	
		China)		requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/03321/25	Hungary	Toy rattle		Choking	Recall of the
		set	5	The product has small parts (koala bear) that	product from
			Rottles and to you	can easily detach. A small child may put them	end users
		(Country of		in their mouth and choke. The product does	
		Origin:		not comply with the requirements of the Toy	
		China)		Safety Directive nor with the relevant	
				European standard EN 71-1.	
SR/03327/25	France	Felt-tip	44.61.84	Choking	Withdrawal of
		pens		The product contains removable parts (the	the product
			Omy FEURES JUMBO	nibs of the pens) that can easily detach. A	from the
		(Country of	SULPATION OF THE PROPERTY OF T	small child may put them in their mouth and	market
		Origin:		choke. The product does not comply with the	
		China)		requirements of the Toy Safety Directive and	
				the relevant European standard EN 71-3.	





Alert No.	Notifying	Product	Product	Hazard/ Risk	Measures
00/00000/05	Country		Photo		Adopted
SR/03328/25	UK	Puzzle toy	-11111111111111111111111111111111111111	Choking	Import rejected
		(0)	A BEDGER 4	Small parts (the puzzle pieces) can easily	at border
		(Country of	OPORSTA	detach. A small child may put them in the	
		Origin:	D V M L V L	mouth and choke on them. The product does	
		China)		not comply with the requirements of the Toy	
	_			Safety Directive.	
SR/03329/25	France	Bottle		Choking	Recall of the
			Wo.	The product contains small parts that can	product from
		(Country of	**	easily detach (the sealing plug). Small children	end users
		Origin:		may put them in their mouth and choke. The	
		China)		product does not comply with the General	
				Product Safety Regulation.	
SR/03331/25	Lithuania	Toy	1	Injuries	Withdrawal of
		pushchair		The pushchair is not sufficiently resistant to	the product
				load. As a consequence, it can easily collapse	from the
		(Country of	10	and a child may fall, leading to injuries. The	market
		Origin:	MM	product does not comply with the	
		China)		requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/03338/25	France	Soft toy		Choking	Withdrawal of
				The toy contains small parts that can easily	the product
		(Country of		detach (the eyes). Small children may put	from the
		Origin:	超又道	them in the mouth and choke. The product	market
		China)		does not comply with the requirements of the	
				Toy Safety Directive, nor with the European	
				standard EN 71-1.	
SR/03339/25	Europe	Toy slime	restor of the latest the same	Chemical	Ban on the
				The migration of boron from the toy slime is	marketing of
		(Country of		too high (measured value up to 705.4 mg/kg).	the product
		Origin:	NON-TEXAS.COM	Ingestion or contact with an excessive quantity	and any
		China)	4	of boron may harm the health of children by	accompanying
				damaging the reproductive system. The	measures
				product does not comply with the	
				requirements of the Toy Safety Directive, nor	
				with the European standard EN 71-3.	





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03340/25	Europe	Toy slime (Country of Origin: China)	* Crisq	Chemical The migration of boron from the toy slime is too high (measured value up to 1181 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-3.	Ban on the marketing of the product and any accompanying measures
SR/03348/25	Ireland	(Country of Origin: China)		Strangulation The toy set features a long cord. This cord can become wrapped around a child's neck during various activities, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive.	Removal of this product listing by the online marketplace
SR/03362/25	Europe	Toy slime (Country of Origin: China)		Chemical The migration of boron from the toy slime is too high (measured value up to 940 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-3.	Ban on the marketing of the product and any accompanying measures
SR/03369/25	France	Keyring (Country of Origin: China)	Hope Sea	Choking The product has a small part that can easily detach (the metal ring). A small child could put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/03376/25	Europe	Toy slime (Country of Origin: China)	CRITIA CRITIA LENG LENG LENG LENG LENG LENG LENG LENG	Chemical The migration of boron from the toy slime is too high (measured value up to 910 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the	Ban on the marketing of the product and any accompanying measures





NEWSLETTER

Issue no.: 40/25/TCD

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				requirements of the Toy Safety Directive, nor	
				with the European standard EN 71-3.	
SR/03378/25	Ireland	Balloon		Injuries	Recall of the
		pumper	A 6 M	The filling pressure may increase upon	product from
				pumping, and the product might rupture	end users
		(Country of		causing a risk of injuries. The product does	
		Origin:		not comply with the requirements of the Toy	
		China)		Safety Directive.	
SR/03384/25	Sweden	Inflatable	SWIM RING	Chemical	Withdrawal of
		swim ring		The plastic material of the product has an	the product
				excessive concentration of bis(2-ethylhexyl)	from the
		(Country of		phthalate (DEHP) and di-'isononyl' phthalate	market
		Origin:	0 0000	(DINP) (measured values: 19.4% and 0.14%	
		China)		by weight, respectively). These phthalates	
				may harm the health by causing possible	
				damage to the reproductive system.	
				Moreover, DINP may cause possible damage	
				to the liver. The product does not comply with	
				the REACH Regulation.	
SR/03389/25	Ireland	Wooden toy		Choking	Removal of
			N Park	The product has small parts (the round	this product
		(Country of		components) that can easily detach. A small	listing by the
		Origin:	10	child may put them in the mouth and choke.	online
		Unknown)	A ON	The product does not comply with the	marketplace
				requirements of the Toy Safety Directive.	

Safety Gate: the EU rapid alert system for dangerous non-food products

"Safety Gate", the EU rapid alert system (formerly known as "RAPEX"), enables the rapid exchange of information between 31 European countries and the European Commission on non-food dangerous products found on the market posing a risk to the health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on https://ec.europa.eu/safety-gatealerts/screen/search?resetSearch=true. The measures taken in the notifying country in order to restrict such products' marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.



Recall Summary – US Toys / Children's Products

CPSC Recall List (Sep 2025)

B # W N	Notifying		B 1 (B) (
Recall No.	Country	Product	Product Photo	Hazard/ Risk	Remedy
25-456	USA	URMYWO		Suffocation and Fall Hazard	Consumers
		Baby		URMYWO Baby Loungers Recalled Due to	should stop
		Loungers		Risk of Serious Injury or Death from	using the baby
				Suffocation and Fall Hazard; Violates	loungers
		(Country of		Mandatory Standard for Infant Sleep	immediately
		Origin:		Products; Sold on Amazon by Pomona	and contact
		China)			Pomona for a
				The baby loungers violate the mandatory	full refund.
				standard for Infant Sleep Products because	Consumers
				the sides are shorter than the minimum	should remove
				side height limit to secure the infant; the	the sleeping
				sleeping pad's thickness exceeds the	pad, cut up the
				maximum limit, posing a suffocation	sides of the
				hazard; and an infant could fall out of an	baby loungers
				enclosed opening at the foot of the lounger	and the
				or become entrapped. The portable	sleeping pad
				loungers do not have a stand, posing a fall	and email a
				hazard. These violations create an unsafe	photo of the
				sleeping environment for infants, posing a	destroyed
				risk of serious injury or death.	lounger
					to urmyworeca
					II@yundnetwor
					k.com to
					obtain a full
					refund.
25-461	USA	Children's	HUNDRED CACTUS BALLS	Choking Hazard	Consumers
		Wooden	36m*)	Shierdu Children's Toys Recalled Due to	should
		Cactus		Risk of Serious Injury or Death from	immediately
		Toys	32	Choking Hazard; Violates the Small Parts	stop using
			A. MARRIAGO	Ban; Sold on Amazon by Yiwu Shiyi	the recalled
		(Country of		Trading	toys and
		Origin:			contact Yiwu
		China)		The recalled toy is intended for children	Shiyi Trading
				under three years of age and contains	for a full



Headquarters - The Hong Kong Standards and Testing Centre Ltd. 👂 10 Dai Wang Street, Tai Po Industrial Estate, Tai Po, N.T., Hong Kong



Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
Recall No. 25-462		In My Jammers Button Up Flare Pajama Sets (Country of Origin: China)	Product Photo	Hazard/ Risk small parts, which violates the small parts ban, posing a deadly choking hazard. Burn Hazard The recalled children's pajama sets violate mandatory standards for children's sleepwear flammability, posing a risk of burn injuries to children.	refund. Consumers will be asked to throw the product away and send a photo of the disposed product to yizhao2025 @outlook.com . Consumers should stop using the recalled pajama sets immediately and contact In My Jammers for a full refund or store credit. Consumers should destroy the pajamas by cutting them in half, then take a photo of the destroyed
					, ·





Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
25-471	USA	Youbeien		To Risk of Serious Injury or Death	Consumers
		Crib		Youbeien Crib Mobiles Recalled Due to	should
		Mobiles	100	Risk of Serious Injury or Death from	immediately
			♦ F	Battery Ingestion; Violates the Mandatory	stop using the
		(Country of	2843	Toy Standard for Batteries; Sold on	recalled toy
		Origin:		Amazon by GKKBSJ	and contact
		China)			GKKBSJ for a
				The recalled toys violate the mandatory	refund.
				standard for toys containing button	Consumers
				batteries because the compartment that	will be asked
				holds the batteries in the remote can be	to throw away
				accessed without the use of a common	the product
				household tool. If button cell or coin	and send a
				batteries are swallowed, the ingested	photo of the
				batteries can cause serious injuries,	disposed
				including internal chemical burns and	product
				death.	to gkkbsjtoys
					@outlook.com
					to receive a
					full refund. If
					consumers
					wish to
					continue using
					the crib
					mobile, they
					can throw
					away only the
					remote and
					send a photo
					of the
					disposed
					remote
					to gkkbsjtoys
					@outlook.com
					to receive a
					refund of \$8.



15



Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
25-472	USA	YooxArmor		To Risk of Serious Injury or Death	Consumers
		Multi-		YooxArmor Multi-Purpose Kids' Helmets	should
		Purpose		Recalled Due to Risk of Serious Injury or	immediately
		Kids'	The same of the sa	Death from Head Injury; Violates	stop using the
		Helmets		Mandatory Standard for Bicycle Helmets;	recalled kids'
				Sold on Amazon by YooxArmor	helmets and
		(Country of			contact
		Origin:		The recalled kids' helmets violate the	YooxArmor for
		China)		mandatory safety standard for bicycle	a full refund.
				helmets because the helmets do not	Consumers
				comply with the impact attenuation,	should destroy
				positional stability, labelling and	the recalled
				certification requirements. The helmets can	helmet by
				fail to protect the user in the event of a	cutting the
				crash, posing a serious risk of injury or	straps off the
				death due to head injury.	helmet.
					Consumers
					can upload
					photos of the
					helmet with
					the straps cut
					off to service
					@yooxarmor.c
					om to obtain a
					refund.
25-473	USA	LXDHSTRA		Suffocation and Fall Hazards	Consumers
		Baby	(A)	LXDHSTRA Baby Loungers and Crib	should
		Loungers	ALCHE	Bumpers Recalled Due to Risk of Serious	immediately
			12502	Injury or Death from Suffocation and Fall	stop using the
		(Country of		Hazards; Violates Federal Standard for	recalled baby
		Origin:		Infant Sleep Products and Federal Crib	loungers and
		China)		Bumper Ban; Sold on Amazon	crib bumpers
					and contact
				The recalled baby loungers violate the	LXDHSTRA
				mandatory standard for Infant Sleep	for a full
				Products. The sides are too low to contain	refund.
				an infant. The sleeping pad is too thick,	Consumers
				posing a suffocation hazard. The enclosed	should remove
				openings at the foot of the loungers are	the foam and





NEWSLETTER

Issue no.: 40/25/TCD

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
				wider than allowed, posing a fall hazard	pads from the
				and an entrapment hazard to infants. Also,	baby lounger's
				the baby loungers do not have a stand,	cover and cut
				posing a fall hazard if it is used on elevated	the cover,
				surfaces. These violations create an	foam, pad, and
				unsafe sleeping environment for infants	crib bumper in
				and can cause death or serious injury to	half.
				infants.	Consumers
					should email
				In addition, the recalled baby loungers	photos of the
				come with crib bumpers, which are banned	destroyed
				by the Federal Safe Sleep for Babies Act	baby lounger
				because the padded crib bumpers can	and crib
				obstruct breathing, posing a risk of serious	bumper
				injury or death to infants from suffocation.	to lxdhstrareca
					II@gmail.com
					to obtain a full
					refund.
25-474	USA	EnHomee		Over and Entrapment Hazards	Consumers
		13-Drawer	TO THE PLANT	EnHomee Dressers Recalled Due to Risk	should
		Dressers	S S S	of Serious Injury or Death from Tip-Over	immediately
			14/2/	and Entrapment; Violates Mandatory	stop using the
		(Country of		Standard for Clothing Storage Units; Sold	recalled
		Origin:		by EnHomee Direct	dressers if
		China)			they are not
				The recalled dressers are unstable if they	anchored to a
				are not anchored to the wall, posing tip-	wall and place
				over and entrapment hazards that can	them in an
				result in serious injuries or death to	area where
				children. The dressers fail to meet the	children
				mandatory standard required by	cannot access
				the STURDY Act.	them. Contact
					EnHomee for
					instructions on
					how to identify
					affected units
					and dispose of
					the dressers to
					receive a full





Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
25-476	USA	Hoovy Cooling Gel Insert Pads for Car Seats and Strollers (Country of Origin: China)	noc	Burn Hazard AMTRADING Recalls Hoovy Cooling Gel Insert Pads for Car Seats and Strollers Due to Burn Hazard The cooling gel pads can become hot if left in the sun or a hot car, posing a burn hazard to young children.	refund. Consumers must submit a photo of the disposed dresser to enhomeesto re@gmail.com . Consumers should immediately stop using the recalled Cooling Gel Insert Pad and contact AMTRADING for instructions on receiving a full refund. Consumers can go to https://hoovypr oducts.com/pa ges/product- recall for instructions on how to register for the recalled
25-477	USA	"RELIEVE" Numbing Cream (Country of Origin:	MAD REBUIT POUR DESCRICTAN POUR DESCRI	Risk of Serious Injury or Death Mad Rabbit Recalls "RELIEVE" Lidocaine Numbing Cream Due to Risk of Serious Injury or Death from Poisoning to Young Children; Violates Mandatory Standard for Child-Resistant Packaging	pad. Consumers should immediately secure the recalled numbing





Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
	USA	Autoez Bamboo Shades (Country of Origin: China)	Product Photo	The numbing cream contains lidocaine, which must be in child-resistant packaging, as required by the Poison Prevention Packaging Act. The numbing cream's packaging is not child-resistant, posing a risk of serious injury or death from poisoning, if the contents are swallowed by young children. Strangulation and Entanglement Hazards Autoez Brand Bamboo Shades Recalled Due to Strangulation and Entanglement Hazards and Risk of Serious Injury or Death; Violates Federal Rule for Window Coverings; Sold on Walmart.com The recalled shades have long operating cords and accessible inner cords that can cause death or serious injury to children, due to strangulation and entanglement hazards. The shades violate the federal rule for window coverings and present a substantial product hazard. In addition, the shades also violate labelling requirements for window coverings.	cream out of the sight and reach of children and contact Mad Rabbit via email or online for a free childresistant lid to store the products. Once the product is secured, consumers can use the product, as directed. Consumers should immediately stop using the recalled shades and contact Autoez for a full refund. Consumers should remove the shades, cut the operating cord, write the word "Recalled" on the shades and dispose of the product in the garbage. Consumers





Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					should send a
					photograph of
					the destroyed
					window
					shades in the
					garbage
					to Autoez_rec
					all@163.com.
25-479	USA	Persilux		Strangulation and Entanglement	Consumers
		Zebra		Hazards	should
		Blinds		Persilux Brand Zebra Blinds Recalled Due	immediately
			UL 727	to Strangulation and Entanglement	stop using the
		(Country of	Y	Hazards and Risk of Serious Injury or	recalled blinds
		Origin:		Death; Violates Federal Rule for Window	and contact
		China)		Coverings; Sold on Amazon	Persilux for a
					free repair kit,
				The recalled blinds have long operating	including
				cords that can cause death or serious	shipping. The
				injury to children, due to strangulation and	repair kit
				entanglement hazards. The blinds violate	consists of a
				the federal rule for window coverings and	replacement
				present a substantial product hazard. In	operating cord
				addition, the blinds also violate labelling	wand and
				requirements for window coverings.	installation
					instructions.
					Consumers
					should remove
					the blind, cut
					and remove
					the operating
					cord and send
					a photograph
					of the blinds,
					with the
					operating cord
					removed,
					to recall@pers
					iluxhome.com.

* Source: www.recalls.gov

20







CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States Government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a "one stop shop" for U.S. Government recalls, http://www.recalls.gov, has been created. Members of the public may report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC's Fast Track Recall programme. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.

warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information

21



Recall Summary – Australian Toys / Children's Products

ACCC Recall List (Sep 2025)

PRA No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
2025/20598	Australia	Fantastic	Tiloto	At Risk of Choking	Immediately
		Four		These products don't comply with the	discontinue use
		Illuminated	THE REAL PROPERTY OF THE PARTY	mandatory standards for products	and keep out of
		Cups		containing button/coin batteries.	reach of
		-			children.
		(Country of		The screw in the battery covering can be	Do not remove
		Origin:	Clare .	removed. This could allow children access	the batteries
		China)		to the button/coin battery.	from the product
		·			and do not
				The screw and/or battery covering could	dispose of the
				also be lost when replacing the battery.	cups.
					Contact Golden
				The products are missing warning	Link Australia
				information about:	Pty Ltd via the
				the dangers of button/coin batteries to	below details to
				children	arrange for the
				What to do when a person suspects	product to be
				someone has swallowed or placed a	returned for
				button/coin battery inside any part of	either a full
				their body.	refund or to
					register for a
				Children are at risk of choking, serious	collectable
				injury or death if they swallow or place	replacement
				button/coin batteries inside their bodies.	cup.
				If you suspect a child has swallowed or	Golden Link
				inserted a button/coin battery:	Australia Pty Ltd
				Call Triple Zero (000) if a child is	Call:1800 583
				having any difficulty breathing.	580
				Call the Poisons Information Centre	Email:
				immediately on 13 11 26, available 24	gla.customerser
				hours a day. They can direct you to an	vice@goldenlink
				appropriate medical facility.	inc.com.au
				Early action can save lives. Do not wait for	
				symptoms to develop.	





	Madifician		Dunadanat		
PRA No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
2025/20621	Australia	Bunjie	THOLO	Risk of Adverse Reaction	Stop using the
2020/20021	Adotrana	Peek-A-Boo	40	The package may not have been properly	product
		Probiotic	Bunjie PEDK-A BOO PROBIOTIC BABY EYE WIPES	sealed during manufacturing, which may	immediately.
		Baby Eye	GOTHNICA TEAR FEEL GOTHNICA TEAR FEEL GOTHNICA STATE AND	lead to mould growth.	Return the
		Wipes		G	product to the
				Risk of allergic reaction and illness,	place of
		(Country of		including skin and eye irritation or infection,	purchase for a
		Origin: New		if mould is present in a wipe that is used on	full refund.
		Zealand)		skin.	Alternatively,
		,			consumers can
				Individuals with sensitive skin or weakened	submit a
				immune systems may be at greater risk.	photograph of
					the product
				Incidents have occurred.	including the
					batch code and
					manufacture
					date directly to
					Bunjie to
					receive a full
					refund or a gift
					card, before
					disposing of the
					product.
					Contact
2025/20626	Australia	Knitted		Risk of Serious Injury or Death	Stop using the
		Animals		These products may not comply with the	toys
				mandatory standard for toys for children up	immediately and
		(Country of		to and including 36 months of age. The	keep them out
		Origin:		product contains small parts that may	of reach of
		Australia)		separate from the toy during play.	children.
					Dispose of the
				There is a risk of serious injury or death	toys.
				from choking if small parts separate from	Contact Ari and
				the toy and small children place them in	Arlo for a full
				their mouth.	refund.
					Contact
					Ari and Arlo
					Email:





PRA No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
	Country				info@ariandarlo
					.com
					Visit:
					https://ariandarl
					o.com
2025/20627	Australia	Helmet for		Risk of Death or Serious Injury	Stop using the
		cycling,		This product doesn't comply with the	helmet
		scooter or		mandatory standard for bicycle helmets.	immediately.
		skateboard	(mbeast)	The buckle is not permanently attached to	Contact
			7/2	the strap and could be removed, making	JetBlack
		(Country of		the helmet unsafe.	Products via
		Origin:			email to arrange
		China)		Risk of death or serious injury in the event	to have your
				of a collision if the buckle is removed from	helmet repaired.
				the retention strap.	Contact
					JetBlack
					Products
					call: (02)
					45601200
					Email:
					info@jetblackpr
					oducts.com
					Visit:
					https://www.jetbl
					ackproducts.co
					m/contact-us/
2025/20630	Australia	CleanLIFE		Risk of Infection or Illness That Might	Stop using
		On the Go 2	GeanLIFE CONTRACTOR	Require Medical Treatment	these wipes
		in 1 wipes	ON THE GO 2 IN 1 WIPES HAND AND SURFACE MANITISER 15	The affected batch of wipes can be	immediately and
			Consider American Consideration Cons	contaminated with bacteria burkholderia	dispose of them
		(Country of		cepacia complex.	in accordance
		Origin:			with local
		Australia)		Risk of infection or illness that might	regulations.
				require medical treatment, especially in	Contact
				people with weakened immune systems	CleanLIFE to
				(immunocompromised) if they are exposed	arrange a full
				to burkholderia cepacia complex bacteria.	refund for the
				The bacteria can enter the body if inhaled,	cost of the
				or through the eyes or a break in the skin.	wipes.





	Notifying		Product		
PRA No.	Country	Product	Photo	Hazard / Risk	Remedy
					Contact
					CleanLIFE
					Call: 08 8124
					7380 between 8
					am and 4 pm
					(ACST) Monday
					to Friday.
					Email:
					ask@cleanlife.c
					om.au
					Visit:
					https://cleanlife.
					com.au/
2025/20634	Australia	Toothy		Risk of Serious Injury or Death	Stop using
		Teether and		The teethers don't comply with the size	these teethers
		Cactus		requirements of the mandatory standard for	immediately and
		Teether	4	toys for children up to and including 36	keep them out
				months of age.	of reach of
		(Country of			children.
		Origin:		Risk of serious injury or death from choking	Return to the
		China)		if the teethers are used without	place of
				supervision.	purchase for a
					refund.
					Contact
					Annabel Trends
					Pty Ltd
					phone: 07 5593
					4755 Monday to
					Friday 8 am to 4
					pm. Closed
					public holidays.
					Email:
					info@annabeltr
					ends.com
					Visit:
					https://www.ann
					abeltrends.com/





PRA No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
2025/20647	Australia	Noisy	noisy rhymes (A) Twinkle, twinkle, little Star	Missing of Warnings	1. Stop using
		Rhymes	interestur.	The products don't comply with the	the products
		Book		mandatory standards for products	immediately and
		Series -		containing button/coin batteries.	keep them out
		contains			of reach of
		button		The products were not tested prior to sale	children.
		batteries		and do not include the required warning	2. Consumers
				information.	should contact
		(Country of			mishmashed to
		Origin:		The products are missing warning	receive the
		China)		information about:	warning
				The dangers of button/coin batteries to	information.
				children	
				What to do when a person suspects	Contact
				someone has swallowed or placed a	mishmashed
				button/coin battery inside any part of	Phone: 03 7006
				their body.	5160, 9:00am to
					4:00pm, AEST
				Children are at risk of choking, serious	Monday to
				injury or death if they swallow or place	Friday
				button/coin batteries inside their bodies.	Email:
					info@mishmash
				If you suspect a child has swallowed or	ed.com.au
				inserted a button/coin battery:	Visit:
				Call Triple Zero (000) if a child is	https://mishmas
				having any difficulty breathing.	hed.com.au/
				Call the Poisons Information Centre	
				immediately on 13 11 26, available 24	
				hours a day. They can direct you to an	
				appropriate medical facility.	
				Early action can save lives. Do not wait for	
				symptoms to develop.	



Australian Product Safety System

The Australian product safety system is set up to maximise the safety of goods through the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritising and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on https://www.productsafety.gov.au/recalls.



Recall Summary - Japanese Toys / Children's Products

METI Recall List (Sep 2025)

Date	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2025-9-1	Japan	自転車	he c	フロントフォークのステムインサート部分に	回収・交換
		(フロン		亀裂が発生する可能性があるため。	
		トフォー			Recall and
		ク)		Cracks can occur in the stem insert part of	replacement
				the front fork.	
		Bicycle			
		(front			
		fork)			
2025-9-8	Japan	玩具	95/1	製品中央にある「らせん エレベーター 」部	回収·返金
				分に子供が指を挟み怪我をする事故が発生し	
		Toy	OSUFE BEALD	たため。	Recall and
					replacement
				An accident occurred in which a child pinched	
				his finger in the "spiral elevator" part of the	
				product and was injured.	

Japan's Product Recall System (業産省 リコール情報)

The METI (経済産業省 Ministry of Economy, Trade and Industry) administers a national recalls system for recalls of specific and general consumer products according to the Consumer Product Safety Act, and publishes all product recalls on the website: https://www.meti.go.jp/product_safety/recall/index.html and posting at https://x.com/kochijiko



NEWSLETTER

Issue no.: 40/25/TCD

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but are not limited to:

EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

US & Canada Requirements

- ASTM F963
- **CPSIA**
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA Toys Regulations (SOR/2011-17)

Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 DEHP

FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: <a href="https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://https://ht Guangdong: gdtcd@stc.group Shanghai: shtcd@stc.group Changzhou: czstc@stc.group Vietnam: vnstc@stc.group ipo@stc.group Japan:

U.S.A.: usenquiry@stc.group grstc@stc.group Germany:

