













## Recall Summary – European Toys / Children’s Products

### EU Safety Gate Alerts (Nov 2025)





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
OR/00160/25	Hungary	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  The fibrous stuffing material of the toy is easily accessible. A small child could put stuffing material in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
OR/00161/25	France	<b>Blanket</b>  (Country of Origin: <b>France</b> )		<b>Choking</b>  Due to the weakness of the seams, in particular where the toy sheep's head is attached to the blanket, the fibrous stuffing material of the toy is easily accessible. A small child may put the filling material in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
OR/00163/25	France	<b>Keyring</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  The fibrous stuffing material of the toy is easily accessible. A small child could put stuffing material in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
SR/03595/25	Slovakia	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The battery compartment can be easily opened without the use of any tools, and the batteries inside are easily accessible. If a child puts them in the mouth, the battery can overheat and release electrolyte, which can be ingested by the child and cause damage to the gastrointestinal tract. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 62115.	Withdrawal of the product from the market

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03851/25	UK	<b>Soft toy</b>  (Country of Origin: <b>Unknown</b> )		<b>Choking</b> Small parts (feet, hands, and eyes) may easily detach from the toy. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive.	Ban on the marketing of the product and any accompanying measures
SR/03863/25	UK	<b>Building blocks toy</b>  (Country of Origin: <b>China</b> )		<b>Health Risk / Other, Injuries</b> The toy contains small magnets with a high magnetic flux. If a child swallows the small magnets, they could attract one another, causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive.	Removal of this product listing by the online marketplace
SR/03864/25	UK	<b>Baby sleeping bag</b>  (Country of Origin: <b>Unknown</b> )		<b>Suffocation</b> The sleeping bag has a hood, which may cover the mouth and/or nose area of the baby. This could lead the child to suffocate. The product does not comply with the General Product Safety Regulation.	Removal of this product listing by the online marketplace
SR/03876/25	Germany	<b>Balloons</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The balloons release an excessive amount of nitrosamines (measured value 0.185 mg/kg) and nitrosatable substances (8.37 mg/kg), which generate nitrosamines. Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in the mouth. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-12.	Removal of this product listing by the online marketplace
SR/03877/25	Germany	<b>Balloons</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The balloons release an excessive amount of nitrosamines (measured value 0.71 mg/kg) and nitrosatable substances (10.44 mg/kg), which generate nitrosamines. Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in the mouth. The product	Removal of this product listing by the online marketplace


Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-12.	
SR/03878/25	UK	<b>Baby sleeping bag</b>  (Country of Origin: <b>Unknown</b> )		<b>Suffocation</b> The sleeping bag has a hood, which may cover the mouth and/or nose area of the baby. This could lead the child to suffocate. The product does not comply with the General Product Safety Regulation.	Removal of this product listing by the online marketplace
SR/03881/25	Lithuania	<b>Squeeze toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy has small parts (balls). Small children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/03882/25	Lithuania	<b>Squeeze toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy has small parts (balls). Small children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/03884/25	Slovakia	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The battery compartment can be easily opened without the use of any tools, and the batteries inside are easily accessible. If a child puts them in the mouth, the battery can overheat and release electrolyte, which can be ingested by the child and cause damage to the gastrointestinal tract. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 62115.	Withdrawal of the product from the market
SR/03885/25	France	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b> The toy contains small parts that can easily detach (carrot, paw piece). Small children may put them in the mouth and choke. Furthermore, the battery compartment can be easily opened without the use of any tools, and the batteries	Recall of the product from end users





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				inside are easily accessible. If a child puts them in the mouth, the battery can overheat and release electrolyte, which can be ingested by the child and cause damage to the gastrointestinal tract. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standards EN 71-1 and EN 62115.	
SR/03893/25	Germany	<b>Balloons</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The balloons release an excessive amount of nitrosamines (measured total value: 0.055 mg/kg), and nitrosatable substances (measured value: 1.17 mg/kg), which generate nitrosamines. Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in the mouth. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-12.	Withdrawal of the product from the market
SR/03900/25	Germany	<b>Balloons</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The balloons release an excessive amount of nitrosamines (measured total value: 0.94 mg/kg), and nitrosatable substances (measured value: 4.56 mg/kg), which generate nitrosamines. Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in the mouth. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-12.	Removal of this product listing by the online marketplace
SR/03929/25	Hungary	<b>Toy rattle</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The product can easily break, releasing small parts (balls). A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users



Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03932/25	Lithuania	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy has small parts (wheels). Small children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/03933/25	UK	<b>Fancy dress costume set</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The product contains small parts (guitar stopper and guitar strap studs) that can easily detach or break, generating small parts. A small child may put these in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive.	Removal of this product listing by the online marketplace
SR/03936/25	Germany	<b>Plush toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Environment</b> The toy contains an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP), dibutyl phthalate (DBP), benzyl butyl phthalate (BBP), diisobutyl phthalate (DIBP), and short-chain chlorinated paraffins (SCCPs) (measured values: up to 25% by weight). The phthalates may harm the health of children, causing possible damage to their reproductive system. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations, and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with the REACH Regulation, the Persistent Organic Pollutants (POP) Regulation, nor with the requirements of the Toy Safety Directive.	Recall of the product from end users
SR/03937/25	Spain	<b>Inflatable mattress</b>  (Country of Origin: <b>China</b> )		<b>Suffocation</b> The plastic bag packaging is too thin. If a child places the plastic bag over their head, they could suffocate. Moreover, the product is lacking mandatory warnings. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures


Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03938/25	Austria	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy contains small parts (hands and feet of the toy monster) that can easily detach. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
SR/03939/25	Hungary	<b>Toy rattle</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy's plastic star can easily break, releasing small parts. A small child may put them in the mouth and choke. Furthermore, the fibrous stuffing material of the toy is easily accessible due to the weakness of the seams. A small child may put the filling material in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/03943/25	Hungary	<b>Rattle set</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> One of the rattles has protruding parts. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
SR/03946/25	Latvia	<b>Musical rattle toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The rattle's bells contain small parts that can easily detach. A small child can put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1	Removal of this product listing by the online marketplace
SR/03950/25	Slovenia	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Burns, Damage to Sight, Fire</b> The batteries of the product become excessively hot, which may result in burns or fire. Moreover, the LED light is too powerful. Looking directly into the light beam may damage the eyesight. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 60825-1 and EN 62115.	Withdrawal of the product from the market





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03955/25	France	<b>Keyring</b>  (Country of Origin: <b>China</b> )		<b>Choking, Injuries, Suffocation</b> The product has a small part that can easily detach (the metal ring). A small child could put it in the mouth and choke. Moreover, the cord is too thin, which may lead to injuries. Furthermore, the plastic bag packaging is too thin. If a child places the plastic bag over their head, they could suffocate. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
SR/03956/25	France	<b>Teether</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The teether has protruding parts. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
SR/03971/25	France	<b>Fancy-dress costume</b>  (Country of Origin: <b>China</b> )		<b>Choking, Strangulation</b> The product has long cords in the neck area. These drawstrings can become trapped during various activities of a child, leading to strangulation. Moreover, the product contains small parts (decorative elements of the crown) that can easily detach or break, generating small parts. A small child may put these in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
SR/03977/25	Germany	<b>Balloons</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The balloons release an excessive amount of nitrosatable substances (measured value: 1.27 mg/kg), which generate nitrosamines. Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in the mouth. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-12.	Withdrawal of the product from the market




Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03978/25	Germany	<b>Balloons</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The balloons release an excessive amount of nitrosamines (measured total value: 0.48 mg/kg), and nitrosatable substances (measured value: 1.81 mg/kg), which generate nitrosamines. Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in the mouth. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-12.	Withdrawal of the product from the market
SR/03983/25	Latvia	<b>Plush toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  The toy contains small parts that can easily detach (black plastic eyes). Small children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
SR/03993/25	Sweden	<b>Remote-controlled toy car</b>  (Country of Origin: <b>China</b> )		<b>Environment</b>  The solders in the product have an excessive concentration of lead (measured value up to 64.6% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
SR/03998/25	Sweden	<b>LED lamp</b>  (Country of Origin: <b>China</b> )		<b>Environment</b>  The solders in the product have an excessive concentration of lead (measured value up to 77.7% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market








Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/04004/25	Sweden	<b>Toy keyboard</b>  (Country of Origin: <b>China</b> )		<b>Environment</b> The solders in the product have an excessive concentration of lead (measured value up to 76.8% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
SR/04017/25	Czechia	<b>Children's slippers</b>  (Country of Origin: <b>Unknown</b> )		<b>Chemical</b> The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 58.7% and 10.7% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. Moreover, the product has an excessive concentration of lead (measured value up to 0.2% by weight). Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity, and may affect breast-fed or unborn children. The product does not comply with the General Product Safety Regulation nor the REACH Regulation.	Stop of sales
SR/04021/25	Latvia	<b>Squeeze toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value: 0.13% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the REACH Regulation.	Removal of this product listing by the online marketplace
SR/04023/25	Sweden	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the doll's head has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 25% by weight). This phthalate may harm health by	Recall of the product from end users






Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				causing possible damage to the reproductive system. The product does not comply with the REACH Regulation, nor with the requirements of the Toy Safety Directive.	
SR/04024/25	Europe	<b>Key ring with soft toy</b>  (Country of Origin: <b>Spain</b> )		<b>Choking</b> The toy has small parts (key ring, eyes, and nose) which may easily detach. A child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
SR/04025/25	France	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Burns</b> The batteries and the toy's switch may overheat and cause burns. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 62115.	Removal of this product listing by the online marketplace
SR/04028/25	Germany	<b>Balloons</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The balloons release an excessive amount of nitrosatable substances (measured value: 1.96 mg/kg), which generate nitrosamines. Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in the mouth. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-12.	Removal of this product listing by the online marketplace
SR/04037/25	France	<b>Fancy-dress costume</b>  (Country of Origin: <b>China</b> )		<b>Burns</b> The blue sequined fabric is highly flammable, and the flame propagation is too high (measured value up to 30 mm/s). The costume may catch fire if worn close to an ignition source, resulting in burns. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-2.	Removal of this product listing by the online marketplace

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/04041/25	Germany	<b>Party decoration set</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The balloons release an excessive amount of nitrosamines (measured total value: 0.08 mg/kg), and nitrosatable substances (measured value: 14.78 mg/kg) which generate nitrosamines. Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in the mouth. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-12.	Removal of this product listing by the online marketplace
SR/04044/25	Latvia	<b>Plush toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  The toy contains small parts that can easily detach (bell, metal hanger). Small children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
SR/04058/25	France	<b>Toy slime</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The migration of boron from the toy slime is too high (measured value: 2937 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-3.	Warning consumers of the risks
SR/04067/25	France	<b>Toy lamp</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b>  The battery compartment can be easily opened without tools, making the button batteries accessible. A child could put the batteries in their mouth, which could cause choking. The batteries can also cause damage to the digestive tract if they are swallowed. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 62115.	Recall of the product from end users





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/04070/25	Slovenia	<b>Toy gun</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b> The battery compartment can be easily opened, leaving the button batteries accessible. A child may put them in the mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. The product does not comply with the requirements of the Toy Safety Directive nor with European standards EN 62115.	Withdrawal of the product from the market
SR/04071/25	Lithuania	<b>Plastic push toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The plastic push toy has small parts (the holder of the push rod). Small children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/04073/25	Finland	<b>Children's car seat</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The product could break apart in the event of a collision, allowing the child's head to move forward more than permitted, which might cause serious or life-threatening injuries to the child's thorax and head. The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components, and separate technical units intended for such vehicles, nor with Regulation UN/ECE No 129.	Recall of the product from end users
SR/04095/25	Latvia	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy has small parts (legs, suction cups) that can easily detach. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
SR/04096/25	Latvia	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking, Strangulation</b> The toy contains small parts (nose, bell, and metal element of the leash) that can easily detach. A small child may put them in the mouth and choke. Moreover, the puppy has long	Removal of this product listing by the online marketplace




Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				strings (red ribbon). These can become entangled around the neck during various activities of a child, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	
SR/04097/25	Latvia	<b>Soother holder</b>  (Country of Origin: <b>China</b> )		<b>Strangulation</b> The cord of the soother holder is too long. It can become wrapped around the neck of the baby, leading to strangulation. The product does not comply with the General Product Safety Regulation nor with the European standard EN 12586.	Removal of this product listing by the online marketplace
SR/04098/25	Latvia	<b>Soother</b>  (Country of Origin: <b>China</b> )		<b>Suffocation</b> The soother does not have the required ventilation holes, leading to suffocation. The product does not comply with the General Product Safety Regulation nor with the European standard EN 1400.	Removal of this product listing by the online marketplace
SR/04101/25	Latvia	<b>Soother</b>  (Country of Origin: <b>China</b> )		<b>Suffocation</b> The soother does not have the required ventilation holes, which could lead to the baby suffocating. The product does not comply with the General Product Safety Regulation nor with the European standard EN 1400.	Removal of this product listing by the online marketplace
SR/04108/25	Ireland	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy contains small parts (eyes) that can easily detach. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive.	Recall of the product from end users
SR/04137/25	Poland	<b>Teether</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The product has small parts (small colourful buttons) which may easily detach. A small child may put them in the mouth and choke. The product does not comply with the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/04145/25	UK	<b>Expandable toy</b>  (Country of Origin: <b>China</b> )		<b>Choking, Injuries</b> The product expands more than 50% in size when in contact with water. If a child puts the product in their mouth or swallows it, contact with saliva or stomach liquids will cause the product to expand, which can result in occlusion of the respiratory tract or intestinal blockage. The product does not comply with the requirements of the Toy Safety Directive.	Removal of this product listing by the online marketplace
SR/04147/25	Sweden	<b>Plush toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value: 24.5% by weight). This phthalate may harm health by causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Removal of this product listing by the online marketplace
SR/04148/25	Poland	<b>Wooden toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy has small parts (wooden drawer handle) that can easily detach. Small children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
SR/04151/25	Lithuania	<b>Toy rattle</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy has protruding parts (rattle handle). A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/04152/25	Lithuania	<b>Set of toy rattles</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy has small parts that can easily detach (rattling balls and pink hearts). A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/04153/25	Luxembourg	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The product contains small parts (one hand and two feet) that can easily detach. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/04154/25	UK	<b>Expandable toy</b>  (Country of Origin: <b>China</b> )		<b>Choking, Injuries</b> The product expands more than 50% in size when in contact with water. If a child puts it in the mouth or swallows it, the contact with saliva or stomach liquids will cause the product to expand, which can result in occlusion of the respiratory tract or intestinal blockage. The product does not comply with the General Product Safety Regulation.	Removal of this product listing by the online marketplace
SR/04155/25	Europe	<b>Finger painting kit</b>  (Country of Origin: <b>China</b> )		<b>Microbiological</b> The total count of aerobic bacteria in the black paint is too high (measured quantity: 200000 cfu/g). These bacteria represent a risk of contracting infections as the product may come in contact with open wounds, mouth, hands, or eyes. The product does not comply with the requirements of the Toy Safety Directive.	Ban on the marketing of the product and any accompanying measures
SR/04159/25	France	<b>Teether</b>  (Country of Origin: <b>China</b> )		<b>Choking, Strangulation</b> The cord can open and become too long. It may wrap around the neck of a baby and lead to strangulation. Moreover, the product can easily break, resulting in small parts. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
SR/04160/25	Germany	<b>Baby bounce swing</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The baby jumper's support strap can break, causing the child to fall and potentially suffer fatal injuries to the head or neck. The product does not comply with the General Product Safety Regulation.	Warning consumers of the risks

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
		Origin: <b>China)</b>		Safety Regulation nor with the European standard EN 14036.	
SR/04161/25	Sweden	<b>Push game toy</b>  (Country of Origin: <b>China)</b>		<b>Environment</b> The solders in the product have excessive concentrations of lead and cadmium (measured values up to 77.5% and 0.28% by weight, respectively). Lead and cadmium pose a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Removal of this product listing by the online marketplace
SR/04165/25	Sweden	<b>Puzzle game</b>  (Country of Origin: <b>China)</b>		<b>Environment</b> The solders in the product have an excessive concentration of cadmium (measured values up to 0.39% by weight). Cadmium poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Removal of this product listing by the online marketplace
SR/04167/25	Sweden	<b>Children's camera</b>  (Country of Origin: <b>China)</b>		<b>Environment</b> The solders in the product have an excessive concentration of cadmium (measured values up to 0.57% by weight). Cadmium poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Removal of this product listing by the online marketplace
SR/04175/25	France	<b>Soft toy</b>  (Country of Origin: <b>China)</b>		<b>Chemical</b> The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 0.48% by weight). This phthalate may harm health by causing possible damage to the reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the REACH Regulation.	Recall of the product from end users



Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/04177/25	France	Ride-on toy  (Country of Origin: Turkey)		<b>Choking, Injuries</b> A small child using this ride-on toy may fall because the toy is not stable and collapses if the rear axle breaks. Furthermore, this could create small parts from the broken plastic fragments of the axle, which the child could get injured by and/or put in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market

## Safety Gate: the EU rapid alert system for dangerous non-food products

“Safety Gate”, the EU rapid alert system (formerly known as “RAPEX”), enables the rapid exchange of information between **31 European countries** and the European Commission on non-food dangerous products found on the market posing a risk to the health and safety of consumers.



A weekly overview of the alerts on those products is published in English for free on <https://ec.europa.eu/safety-gate-alerts/screen/search?resetSearch=true>. The measures taken in the notifying country in order to restrict such products’ marketing or use can be ordered by national authorities (“compulsory measures”) or be taken directly by producers and distributors (“voluntary measures”).


The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (**2001/95/EC**) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

## Recall Summary – US Toys / Children’s Products


### CPSC Recall List (Nov 2025)



Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
26-069	USA	<b>Criblike aftermarket play yard and non-full-sized crib mattresses</b>  (Country of Origin: <b>China</b> )		<b>Risk of Serious Injury or Death</b> Criblike Mattresses Recalled Due to Risk of Serious Injury or Death from Entrapment or Suffocation; Violates Mandatory Standards for Mattresses; Sold on Amazon by Mengna.  Criblike aftermarket play yard and non-full-sized crib mattresses.	Consumers should immediately stop using the crib mattresses and contact Criblike for instructions on requesting a full refund. Consumers should destroy the mattresses by cutting them in half, take a photo of the destroyed mattress, and email the photo to Criblike-service_2025@outlook.com with “Recall Proof” and your name in the subject line.

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
26-070	USA	<b>Three-Wheeled Children's Scooter with Foot Brake</b>  (Country of Origin: <b>China</b> )		<b>Fall Hazard</b> Three-Wheeled Children's Scooters Recalled Due to Fall Hazard; Imported by Konges Sløjd.  The left front wheel can detach during use, posing a fall hazard.	Consumers should stop using the scooter immediately and contact Konges Sløjd for a full refund or voucher by either providing a photo of the scooter disassembled by removing the scooter stem from the base of the scooter or returning the unit to the store where it was purchased.
26-071	USA	<b>Napei Collapsible Infant Bath Tubs</b>  (Country of Origin: <b>China</b> )		<b>Ingestion Hazard</b> Napei Infant Bath Tubs Recalled Due to Risk of Serious Injury or Death from Ingestion Hazard; Violates Mandatory Standard for Consumer Products with Button Cell Batteries; Sold on Amazon by Sefon Store.  The recalled infant bath tubs violate the mandatory standard for consumer products containing button cell or coin batteries because the built-in thermometer contains button cell batteries that can be accessed easily by children. When button cell or coin batteries are swallowed, the ingested batteries can cause	Consumers should immediately stop using the infant bath tubs and contact Sefon Store for instructions to receive a free replacement battery compartment. Consumers should provide


Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
				serious injuries, internal chemical burns, and death.	their order number or a photo of the tracking label found on the bottom of the infant bath tub and email Sefon Store at Napeiservic e00@outlook.com. Upon confirmation of your order number or a photo of the tracking label, Sefon Store will provide a replacement battery compartment to be delivered to the consumer.
26-073	USA	<b>Umeyda Nightgowns</b>  (Country of Origin: <b>China</b> )		<b>Risk of Serious Injury or Death</b> Umeyda Nightgowns Recalled Due to Risk of Serious Injury or Death from Burns; Violate Mandatory Standards for Children's Sleepwear; Sold on Amazon by Umeyda Company.  The recalled nightgowns violate the mandatory flammability standards for children's sleepwear, posing a risk of burn injuries to children.	Consumers should stop using the nightgowns immediately and contact Umeyda Company for a full refund. Consumers should cut the nightgowns in half and email





Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					a photo of the destroyed garments to ameyda123@163.com to receive the refund. Consumers should dispose of the destroyed garments.
26-074	USA	<b>Vevor Baby Swings</b>  (Country of Origin: <b>China</b> )		<b>Suffocation Hazard</b> Sanven Technology Recalls Vevor Baby Swings Due to Risk of Serious Injury from Suffocation Hazard; Violates Mandatory Standard for Infant Sleep Products and Inclined Sleepers Ban.  The swings were marketed for infant sleep and have an incline angle greater than 10 degrees, violating the mandatory safety standard for Infant Sleep Products and the ban on inclined sleepers under the Safe Sleep for Babies Act, posing a deadly suffocation risk.	Consumers should immediately stop using the swings and contact Sanven Technology for a full refund. Consumers should remove the swing cover and cut it in half, and send a photo of the destroyed cover with "Recalled" written with a permanent marker on the swing's base to recalling@vevor.com, and then dispose of



Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					the swing in accordance with local and state laws.
26-075	USA	<b>Inkari Plush Alpaca Toys</b>  (Country of Origin: <b>Peru</b> )		<b>Choking Hazard</b> Inkari Plush Alpaca Toys Recalled Due to Risk of Serious Injury or Death from Choking Hazard; Violate Small Parts Ban; Imported by Inkari.  The recalled toys are intended for children under three years of age, and the eyes can detach, which violates the small parts ban, posing a choking hazard to children.	Consumers should immediately stop using the recalled plush toys and contact Inkari for a full refund. Consumers will be asked to cut the fur of the toy and send a photo to support@inkari-alpaca.com.
26-081	USA	<b>Children's WYBITNY Bed Rails</b>  (Country of Origin: <b>China</b> )		<b>Risk of Serious Injury or Death</b> WYBITNY Bed Rails Recalled Due to Risk of Serious Injury or Death from Entrapment; Violates Mandatory Standard for Children's Portable Bed Rails; Sold on Amazon by WYBITNY.  The recalled bed rails violate the mandatory standard for children's portable bed rails because, when installed adjacent to the bed, the child can become entrapped in the enclosed openings, the openings on the side of the mattress, and the openings on top of the mattress, posing a risk of serious injury or death due to entrapment.	Consumers should immediately stop using the recalled bed rails and contact WYBITNY for a full refund. Consumers should send a photo of the recalled bed rails, with "Recalled" written on the front in permanent marker, to WYBITNY


Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					by email at servicewybitny@outlook.com. Consumers should dispose of the recalled bed rails in accordance with state and local waste disposal procedures.
26-085	USA	<b>Bettina Doll Set with Magic Light Unicorn</b>  (Country of Origin: <b>China</b> )		<b>Risk of Serious Injury or Death</b> Bettina Doll Sets Recalled Due to Risk of Serious Injury or Death from Battery Ingestion; Violates Mandatory Standard for Toys; Sold on Amazon by Shantou Chenghai Xingzigu Toy Industry.  The doll sets violate the mandatory standard for toys because the battery compartment of the unicorn contains button cell batteries that can be easily accessed by children. When button cell or coin batteries are swallowed, the ingested batteries can cause serious injuries, internal chemical burns, and death.	Consumers should immediately take the doll sets away from children, stop using the recalled toys, and remove and properly dispose of the batteries. Consumers will be asked to throw the unicorn away and send a photo of the disposed product to bettinafersales@outlook.com to receive a full refund.



Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
26-086	USA	<b>Zippee Activity Toys</b>  (Country of Origin: <b>China</b> )		<b>Choking Hazard</b> Zippee Silicone Activity Toys Recalled Due to Risk of Serious Injury or Death from Choking; Violates Mandatory Standard for Toys; Imported by Mobi Games.  The recalled silicone activity toys contain spherical ends that can reach the back of the throat, posing a serious choking hazard to children.	Consumers should stop using the recalled toy immediately, take it away from children, and contact Mobi Games to receive a full refund. Consumers will be asked to register their product online by first confirming they have an affected version with spherical ends on the strings and then by providing a photo of the destroyed toy. Consumers will be directed to destroy the toy by cutting the spherical ends off the silicone strings and writing their initials and date on the teal cylinder.



Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
26-088	USA	<b>Trek and Electra-branded Bicycles with Coaster Brakes and Replacement Rear Wheels with Coaster Brakes</b>  (Country of Origin: <b>China</b> )		<b>Crash Hazard</b> Trek Recalls Bicycles with Coaster Brakes and Replacement Rear Wheels Due to Crash Hazard.  The coaster brakes can fail to engage, resulting in the rider losing control, posing a crash hazard.	Consumers should immediately stop using the recalled bicycles with coaster brakes and related replacement rear wheels and contact an authorized Trek or Electra dealer to schedule a free repair at the dealer.
26-091	USA	<b>Zigjoy Toddler Sleep Sacks with Feet</b>  (Country of Origin: <b>China</b> )		<b>Burn Hazard</b> Zigjoy Sleep Sacks with Feet Recalled Due to Risk of Serious Injury or Death from Burn Hazard; Violates Mandatory Standard for Children's Sleepwear; Sold by Zigjoy-US.  The recalled sleep sacks violate the mandatory flammability standard for children's sleepwear, posing a burn hazard and risk of serious injury or death to children.	Consumers should immediately stop using the sleep sacks and contact Zigjoy-US for a full refund. Consumers should cut the sleep sacks in half, take a photo of the destroyed garments, and email it to zjoy-us@outlook.com to receive the refund.

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
26-094	USA	<b>4-in-1 Baby Safety Cart Carriage</b>  (Country of Origin: <b>China</b> )		<b>Risk of Serious Injury or Deadly Fall Hazard</b> The stroller violates the mandatory standard for strollers because the restraint system can fail, posing a risk of serious injury or a deadly fall hazard.  This recall involves a stroller that converts into a hand-held infant carrier. The product was sold in pink, light pink, blue, dark blue, green, red, teal, grey, and black, and comes with a grey or black infant insert. The two larger wheels feature yellow accents. There are no markings on the product.	Consumers should immediately stop using the recalled stroller and contact AliExpress to receive a full refund. Consumers will be required to cut the restraints and email a photo of the destroyed product to <a href="mailto:us_product_recall@aliexpress.com">us_product_recall@aliexpress.com</a> .
26-095	USA	<b>Bearlala Baby Loungers</b>  (Country of Origin: <b>China</b> )		<b>Entrapment and Fall Hazards</b> Bearlala Baby Loungers Recalled Due to Risk of Serious Injury or Death from Entrapment and Fall Hazards; Violates Mandatory Standard for Infant Sleep Products; Sold on Walmart.com by Nuoxuann.  The recalled baby loungers violate the mandatory standard for Infant Sleep Products. The sides are too low to contain an infant. The enclosed openings at the foot of the loungers are wider than allowed, posing fall and entrapment hazards to infants. In addition, the baby loungers do not have a stand, posing a fall hazard if used on elevated surfaces. These violations create an unsafe sleeping environment and can cause death or serious injury to infants.	Consumers should immediately stop using the recalled baby loungers and contact Nuoxuann for a full refund. Consumers should remove the foam and pads from the baby lounger's cover and cut the cover, foam, and pad in half. Consumers


Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					should email photos of the destroyed pieces to Recall-nuoxuann@outlook.com to obtain a full refund.
26-096	USA	<b>Grow 'N Stow Folding Learning Tower</b>  (Country of Origin: <b>China</b> )		<b>Fall Hazard</b> Little Partners Recalls Children's Grow 'N Stow Folding Learning Towers Due to Fall Hazard.  The platform inside the tower can collapse, posing a fall hazard to young children.	Consumers should immediately stop using the recalled Grow 'N Stow Folding Learning Tower, keep it away from children, and contact Little Partners to receive a free repair kit, which includes a new crossbar with pin tabs and installation instructions. The new crossbar will have a sticker indicating that it is no longer part of the recall. Consumers should remove the old


Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					crossbar and dispose of it.
26-099	USA	<b>Play Yards</b>  (Country of Origin: <b>China</b> )		<b>Suffocation and Entrapment Hazards</b> Play Yards Recalled Due to Risk of Serious Injury or Death from Suffocation and Entrapment Hazards; Violate Mandatory Standard for Play Yards; Sold on Amazon by Anna Queen  The play yards violate the mandatory standard for play yards. Infants can become entrapped under the mattress or between the side of the play yard and the mattress, posing a risk of serious injury or a deadly suffocation hazard.	Consumers should immediately stop using the recalled play yards and contact Anna Queen for a full refund. Consumers should disassemble the fabric cover from the play yard frame, cut up the cover and mattress pad, and email a photo of the destroyed play yard to <a href="mailto:tingerservice@outlook.com">tingerservice@outlook.com</a> to obtain a full refund. Consumers should then dispose of the destroyed play yard.
26-101	USA	<b>Mallimoda Children's Pajama Sets</b>  (Country of		<b>Burn Hazard</b> Mallimoda Children's Pajama Sets Recalled Due to Risk of Serious Injury or Death from Burn Hazard; Violates Mandatory Standards for Children's Sleepwear; Sold on Amazon by Mallimoda	Consumers should immediately stop using the recalled pajama sets



Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
		Origin: <b>China)</b>		The recalled pajama sets violate the mandatory standards for children's sleepwear, posing a risk of serious injuries or a deadly burn hazard to children.	and contact Mallimoda for a full refund. Consumers should cut the pajama sets in half and email a photo of the destroyed garments to mallimodarecall@hotmail.com with the consumer's name and "Recall Proof" in the subject line.
26-104	USA	<b>Anzmtosn Magnet Fidget Spinner Sets</b>  (Country of Origin: <b>China)</b>		<b>Ingestion Hazard</b> Magnet Fidget Spinner Sets Recalled Due to Risk of Serious Injury or Death from Magnet Ingestion; Violates Mandatory Standard for Toys; Sold on Amazon by Anzmtosn  The recalled magnet spinner sets violate the mandatory standard for toys because the sets contain loose magnets, posing an ingestion hazard to children. When high-powered magnets are swallowed, they can attract each other, or other metal objects, and become lodged in the digestive system. This can result in perforations, twisting, and/or blockage of the intestines, blood poisoning, and death.	Consumers should stop using the recalled magnetic fidget spinner sets immediately, take them away from children and dispose of them. To receive a full refund, consumers should send a photo of the disposal to Anzmtosn via email



Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					at Anzmtosn53@163.com.
26-112	USA	<b>Alinux Baby Loungers</b>  (Country of Origin: <b>China</b> )		<p><b>Entrapment and Fall Hazards</b></p> <p>Alinux Baby Loungers Recalled Due to Risk of Serious Injury or Death from Entrapment and Fall Hazards; Violates Mandatory Standard for Infant Sleep Products; Sold on Amazon by Winkids</p> <p>The recalled baby loungers violate the mandatory safety standard for Infant Sleep Products. The sides are too low to contain an infant, and the enclosed openings at the foot of the loungers are wider than allowed, posing serious risks of fall and entrapment hazards to infants. In addition, the baby loungers do not have a stand, posing a fall hazard if used on elevated surfaces. These violations create an unsafe sleeping environment and can cause death or serious injury to infants.</p>	<p>Consumers should immediately stop using the recalled baby loungers and contact Winkids for a full refund.</p> <p>Consumers should remove the foam and pads from the baby lounger's cover and cut the cover, foam, and pad in half.</p> <p>Consumers should email photos of the destroyed pieces to alinuxrecall@163.com to obtain a full refund.</p>
26-113	USA	<b>Macardac Baby Loungers</b>  (Country of Origin: <b>China</b> )		<p><b>Entrapment and Fall Hazards</b></p> <p>Macardac Baby Loungers Recalled Due to Risk of Serious Injury or Death from Entrapment and Fall Hazards; Violates Mandatory Standard for Infant Sleep Products; Sold on Amazon by Macardac Products</p> <p>The recalled baby loungers violate the mandatory safety standard for Infant Sleep Products. The sides are too low to contain an</p>	<p>Consumers should immediately stop using the recalled baby loungers and contact Macardac Products for a full refund.</p>

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
				<p>infant, and the enclosed openings at the foot of the loungers are wider than allowed, posing serious risks of fall and entrapment hazards to infants. In addition, the baby loungers do not have a stand, posing a fall hazard if used on elevated surfaces. These violations create an unsafe sleeping environment and can cause death or serious injury.</p>	<p>Consumers should remove the foam and pads from the baby lounger's cover and cut the cover, foam, and pad in half. Consumers should email photos of the destroyed pieces to macardacre call@gmail.com to obtain a full refund.</p>
26-114	USA	<b>Ikuso Safety Gates</b>  (Country of Origin: <b>China</b> )		<p><b>Risk of Serious Injury or Death</b></p> <p>Ikuso Safety Gates Recalled Due to Risk of Serious Injury or Death to Children from Entrapment; Violates Mandatory Standard for Gates and Enclosures; Sold on Amazon by Ikuso</p> <p>The recalled gates violate the mandatory standard for expansion gates and expandable enclosures because a child's torso can fit through the opening between the gate slat and the side wall, posing a risk of serious injury or death due to entrapment.</p>	<p>Consumers should immediately stop using the recalled safety gates and contact Ikuso to request a full refund. Consumers should send a photo of the recalled safety gates, with "Recalled" written on the front in permanent marker, to Ikuso at ikuso_door_</p>

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					gate@163.com . Consumers should dispose of the recalled safety gates in accordance with state and local waste disposal procedures.
26-116	USA	<b>Sofoliana and Glotika Baby Loungers</b>  (Country of Origin: <b>China</b> )		<b>Entrapment and Fall Hazards</b> Sofoliana and Glotika Baby Loungers Recalled Due to Risk of Serious Injury or Death from Entrapment and Fall Hazards; Violates Mandatory Standard for Infant Sleep Products; Sold on Amazon by Bosen US  The recalled baby loungers violate the mandatory safety standard for Infant Sleep Products. The sides are too low to contain an infant, and the enclosed openings at the foot of the loungers are wider than allowed, posing serious risks of fall and entrapment hazards to infants. In addition, the baby loungers do not have a stand, posing a fall hazard if used on elevated surfaces. These violations create an unsafe sleeping environment and can cause death or serious injury.	Consumers should immediately stop using the recalled baby loungers and contact Bosen US for a full refund. Consumers should remove the foam and pad from the baby lounger's cover and cut the cover, foam, and pad in half. Consumers should email photos of the destroyed pieces to BosenRecall@outlook.com to receive a full refund.

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
26-121	USA	<b>Baby High Chairs (convertible)</b>  (Country of Origin: <b>China</b> )		<b>Fall and Entrapment Hazards</b> Convertible High Chairs Recalled Due to Risk of Serious Injury or Death from Fall and Entrapment Hazards; Violate Mandatory Standard for High Chairs; Sold on Amazon by Rotinyard.  The high chairs violate the mandatory standard for high chairs because they were sold without the required attached restraint system, posing a deadly fall hazard to babies. In addition, a child's head can become trapped in the opening between the seat and tray, posing a deadly entrapment hazard.	Consumers should immediately stop using the recalled high chairs and contact Rotinyard for a full refund. Consumers should disassemble the high chairs, cut the restraints and fabric seat cushion insert, and email photos of the destroyed restraints and cushion to trailblazera mz@outlook.com. Once the photos are received, Rotinyard will issue a full refund.
26-122	USA	<b>Outdoor Master Children's and Youth Helmets</b>  (Country of Origin: <b>China</b> )		<b>Risk of Serious Injury or Death</b> Outdoor Master Children's and Youth Helmets Recalled Due to Risk of Serious Injury or Death from Head Injury; Violates Mandatory Standard for Bicycle Helmets; Sold and Imported by Outdoor Master  The recalled children's and youth helmets violate the mandatory safety standard for bicycle	Consumers should immediately stop using the recalled helmets and contact Outdoor Master for

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
				helmets. Particularly, the helmets do not comply with the positional stability and coverage requirements. The helmets can fail to protect the user in the event of a crash, posing a risk of injury or death due to head injury.	instructions on how to register for a full refund.

## CPSC



The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States Government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a “one stop shop” for U.S. Government recalls, <http://www.recalls.gov>, has been created. Members of the public may report unsafe products to CPSC by using the platform.


The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC’s Fast Track Recall programme. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.





## Recall Summary – Australian Toys / Children’s Products


**ACCC Recall List (Nov 2025)**

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2025/20671	Australia	<b>S-Mitter remote for cabinet and kitchen LED lighting systems</b>  (Country of Origin: <b>China</b> )		<b>Risk of Choking</b> The remote doesn't comply with the mandatory standard for products containing button/coin batteries.  The battery isn't secured, and children could access the button/coin battery.  The remote is missing warning information about the dangers of button/coin batteries to children what to do when a person suspects someone has swallowed or placed a button/coin battery inside any part of their body.  Children are at risk of choking, severe internal burn injuries, or death if they swallow or place button/coin batteries inside their bodies.  Serious injury can occur in as little as 2 hours, and the results can be fatal. In Australia, children have suffered serious injuries or died from swallowing button/coin batteries.	Stop using the remote immediately and place out of reach of children. Return the remote to Hettich or the place of purchase for a free replacement with a compliant remote.  Contact Hettich Australia Call: 1800 687 789 Email: support-au@hettich.com Visit: <a href="https://designwithhettich.au/">https://designwithhettich.au/</a>
2025/20689	Australia	<b>Various Miniso light-up keychains, night lights and toys</b>		<b>Risk of Choking</b> The products do not comply with the mandatory standards for products containing button/coin batteries.  The battery may not be secured, and children	Stop using the product immediately and keep it out of reach of children.

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
		(Country of Origin: <b>China</b> )		<p>could access the button/coin battery.</p> <p>The products are missing warning information about the dangers of button/coin batteries to children what to do when a person suspects someone has swallowed or placed a button/coin battery inside any part of their body.</p> <p>Children are at risk of choking, severe internal burn injuries, or death if they swallow or place button or coin batteries inside their bodies.</p> <p>Serious injury can occur in as little as 2 hours, and the results can be fatal. In Australia, children have suffered serious injuries or died from swallowing button/coin batteries.</p>	<p>Return the product to a Miniso store for a full refund.</p> <p>Contact Miniso Winky Australia Pty Ltd call: 0452 253 533 between 10:00 am and 12:00 pm and 2:00 pm to 5:00 pm, Monday to Friday email: feedback@miniso-au.com</p>
2025/20691	Australia	<b>Educational Colours - Rainbow Sand (1.3kg), Creatistics - Coloured Sand (1kg) and Kadink - Coloured Decorative Sand (1.3kg)</b>  (Country of Origin: <b>China</b> )		<p><b>Hazard of Prohibited Substance</b></p> <p>The products are being recalled because they may include asbestos, which is a prohibited substance in Australia.</p> <p>The products may cause a risk to health as tremolite asbestos (a naturally occurring asbestos) has been detected in some samples after laboratory testing.</p> <p>Importantly, respiratory asbestos has not been detected in any of the tested samples. The release of respiratory asbestos fibres from the sand is unlikely to occur in its current state, unless the sand is processed by mechanical means such as crushing or pulverising.</p> <p>While the risk that any asbestos found is likely to</p>	<p>Stop using the products immediately. For safe disposal advice from the Asbestos and Silica Safety and Eradication Agency, visit the ACCC Product Safety website.</p>


PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
				be airborne or fine enough for inhalation is low, this may still pose a risk.	
2025/20692	Australia	<b>Kadink Decorative Sand 10g 6 pack</b>  (Country of Origin: <b>Nationally Online</b> )		<b>Hazard of Prohibited Substance</b> The product is being recalled because the sand may include asbestos, which is a prohibited substance in Australia.  The product may cause a risk to health as asbestos has been detected in some samples after laboratory testing.  Importantly, respirable asbestos has not been detected in any of the tested samples. The release of respirable asbestos fibres is unlikely to occur in its current state, unless the sand is processed by mechanical means such as crushing or pulverising.  The risk that any asbestos found is likely to be airborne or fine enough for inhalation is low.	Stop using the product immediately. Wear disposable gloves and a mask and place the sand in a heavy-duty plastic bag and double-tape it securely, and keep it out of reach of children. Do not dispose of the products in general waste. Information on the disposal of asbestos waste, including disposal facilities in your state or territory, can be found on the Asbestos and Silica Safety and Eradication Agency website.



PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2025/20694	Australia	<b>Beat The Clock Stopwatch Set</b>  (Country of Origin: <b>China</b> )		<b>Risk of Choking</b> The stopwatch doesn't comply with the mandatory standard for products containing button/coin batteries.  The battery isn't secured, and children could access the button/coin battery.  Children are at risk of choking, severe internal burn injuries, or death if they swallow or place button/coin batteries inside their bodies.  Serious injury can occur in as little as 2 hours, and the results can be fatal. In Australia, children have suffered serious injuries or died from swallowing button/coin batteries.	Stop using the product immediately and place it out of reach of children. Return the product to the place of purchase for a full refund.  Contact  Tiger Tribe email: sales@tigertribe.com.au call: 03 9809 4897 Monday to Friday 9.30 am to 3:00 pm
2025/20695	Australia	<b>Coaster brakes on some Trek Precaliber bicycle and service wheel models.</b>  (Country of Origin: <b>Cambodia</b> )		<b>Risk of accident and serious injury</b> The grease inside the coaster brakes does not adequately lubricate the surface, which could cause the brakes to wear faster and damage the brakes.  Risk of accident and serious injury if the brakes fail during use and causing a fall.	Stop using the affected Trek Precaliber bicycles and service wheels immediately. To determine if your bicycle is included in this recall, enter your bicycle's serial number in the look-up tool at <a href="https://www.trek.com">https://www.trek.com</a>

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					<p>kbikes.com/au/en_AU/coaster-brake-recall-inquiry/EYour bicycle's serial number begins with WTU and is located on the bottom bracket near the crankset (located underneath the bicycle near the pedals). If you are unsure whether your bicycle is affected by this recall, please contact your local Trek retailer. Take the bicycle to your nearest Trek retailer to be inspected. The rear wheel will be replaced with a new wheel free of charge.</p>
2025/20696	Australia	<b>Anko Pop and Surprise Playset</b>  (Country of		<b>Choking Hazard</b>  The product does not comply with the mandatory standard for toys for children up to and including 36 months of age.  Small screws may separate from the toy and become a choking hazard.	<p>Stop using this toy immediately and keep out of reach of children. Return the toy</p>



PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
		Origin: <b>Vietnam)</b>		Risk of serious injury or death by choking if small parts separate from the toy and a child places them in their mouth.  Incidents have occurred.	to the place of purchase for a full refund.
2025/20699	Australia	<b>Follow Pop Kids Towelie – item number F13730</b>  (Country of Origin: <b>China)</b>		<b>Risk of Serious Burn Injuries</b> These products don't comply with the mandatory standard for nightwear for children.  The products do not have the required fire hazard label.  There is a risk of serious burn injuries if the product is exposed to a heat or flame source.  Consumers may not be aware of this hazard.	Stop using the towel immediately and keep the product away from heat sources or flame. Return products to the place of purchase for a full refund.
2025/20700	Australia	<b>Active Sandtub 14 piece Sand Castle Building Set; Blue Magic Sand; Green Magic Sand; Pink Magic Sand - sold at Kmart and Target</b>  (Country of Origin: - <b>China)</b>		<b>Hazard of Prohibited Substance</b> The products are being recalled because the sand may include asbestos, which is a prohibited substance in Australia.  The products may cause a risk to health as asbestos has been detected in some samples after laboratory testing.  Importantly, respirable asbestos has not been detected in any of the tested samples. The release of respirable asbestos fibres is unlikely to occur in its current state, unless the sand is processed by mechanical means such as crushing or pulverising.  The risk that any asbestos found is likely to be airborne or fine enough for inhalation is low.	Stop using the products immediately. For safe disposal advice from the Asbestos and Silica Safety and Eradication Agency, visit the ACCC Product Safety website.

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2025/20702	Australia	<b>Glow Shimmer Body Oil &amp; Sunkissed Essential Oil Perfume</b>  (Country of Origin: <b>Australia</b> )		<b>Risk of Serious Sunburn</b>  The affected products' labels do not contain the caution statement that the product may cause increased skin sensitivity to sunlight.  Risk of serious sunburn if the product is applied prior to sun exposure.	Stop using the product immediately. Return the product to the place of purchase for a full refund.
2025/20706	Australia	<b>Licensed 4 in 1 Frame Tray Puzzles</b>  (Country of Origin: <b>China</b> )		<b>Risk of Adverse Reaction</b>  Mould growth may be present in the packaging of the product.  Risk of infection, allergic reactions, or respiratory irritation in children or people with weakened immune systems (immunocompromised) if they are exposed to mould.	Stop using the product immediately and place out of reach of children or immunocompromised people. Return the product and the packaging to Chemist Warehouse for a full refund.
2025/20710	Australia	<b>MIKI Sand Art Set</b>  (Country of Origin: <b>China</b> )		<b>Hazard of Prohibited Substance</b>  The products are being recalled because the sand may contain asbestos, which is a prohibited substance in Australia.  The products may cause a risk to health as initial testing found unidentified mineral fibres that were consistent with tremolite – type asbestos.	Stop using the products immediately. For safe disposal advice from the Asbestos and Silica Safety and Eradication Agency, visit the ACCC Product Safety website.

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2025/20732	Australia	<b>Various coloured sand and sand art party packs</b>  (Country of Origin: <b>China</b> )		<b>Hazard of Prohibited Substance</b> The products are being recalled because the sand may contain asbestos, which is a prohibited substance in Australia.  The products may cause a risk to health, as initial testing in some samples found chrysotile asbestos and unidentified mineral fibres that could be consistent with tremolite asbestos.	Stop using the products immediately. For safe disposal advice from the Asbestos and Silica Safety and Eradication Agency, visit the ACCC Product Safety website.
2025/20733	Australia	<b>K Mini Noodle Critters – squishy toy</b>  (Country of Origin: <b>China</b> )		<b>Risk of Choking</b> These squishy toys don't comply with the mandatory standards for products containing button/coin batteries.  The products were not tested prior to supply.  The products are missing warning information about:  The dangers of button/coin batteries to children what to do when a person suspects someone has swallowed or placed a button/coin battery inside any part of their body.  Children are at risk of choking, serious injury or death if they swallow or place button/coin batteries inside their bodies.	Stop using the product immediately and keep it out of reach of children. Return these products to a Kaisercraft store for a full refund.

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2025/20737	Australia	<b>Montessori Sand Tray Writing Activity Set</b>  (Country of Origin: <b>China</b> )		<b>Hazard of Prohibited Substance</b> The product is being recalled because the sand may contain asbestos, which is a prohibited substance in Australia.  The product may cause a risk to health as trace amounts of tremolite asbestos have been detected in some samples after laboratory testing.	Stop using the product immediately. For safe disposal advice from the Asbestos and Silica Safety and Eradication Agency, visit the ACCC Product Safety website.

## Australian Product Safety System

The Australian product safety system is set up to maximise the safety of goods through the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritising and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on <https://www.productsafety.gov.au/recalls>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but are not limited to:

### EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

### US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

### Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

### Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: [hktcd@stc.group](mailto:hktcd@stc.group)  
Changzhou: [czstc@stc.group](mailto:czstc@stc.group)  
U.S.A.: [usenquiry@stc.group](mailto:usenquiry@stc.group)

Guangdong: [gdtcd@stc.group](mailto:gdtcd@stc.group)  
Vietnam: [vnstc@stc.group](mailto:vnstc@stc.group)  
Germany: [grstc@stc.group](mailto:grstc@stc.group)

Shanghai: [shtcd@stc.group](mailto:shtcd@stc.group)  
Japan: [jpo@stc.group](mailto:jpo@stc.group)

