










Recall Summary – European Toys





Published: 23 July 2021
EU Safety Gate Alerts (July 2021)

Alert No.	Notifying Country	Product	Product Photo	Hazard / Risk	Measures Adopted
A11/00039/21	France	Play Frame with Slide and Swings (Country of Origin: France)		Entrapment, Injury The toy has partially closed openings and accessible holes which can cause injuries to children or in which children's fingers can be trapped. The product does not comply with the requirements of the Toy Safety Directive active and the relevant European standard EN 71-8.	Making the marketing of the product subject to prior conditions
A12/00747/21	Poland	Plastic Doll with Accessories (Country of Origin: Unknown)		Chemical The plastic material of the product contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 1.89% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00748/21	Bulgaria	Sleep Bag (Country of Origin: Bulgaria)		Choking The puller of the slide fastener (zip) could detach as a small part. A child could put it in the mouth and choke. The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 16781:2018.	Withdrawal of the product from the market
A12/00749/21	Belgium	Bedside Sleeper (Country of Origin: Latvia)		Injury The adjustable side of the bedside sleeper can be set at a level which is too low. There is no mechanism to secure the co-sleeper to the bed. As a consequence, the baby in the bedside sleeper may fall and suffer from injuries. The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 1130.	Recall of the product from end users

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00753/21	Bulgaria	Sleep Bag (Country of Origin: Bulgaria)		Choking The puller of the slide fastener (zip) could detach as a small part. A child could put it in the mouth and choke. The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 16781:2018.	Withdrawal of the product from the market
A12/00757/21	Poland	Set of Plastic Dolls with Accessories (Country of Origin: China)		Chemical The plastic material of the toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: up to 19.4% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00758/21	Poland	Plastic Doll with Accessories (Country of Origin: Unknown)		Chemical The plastic material of the toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 10.3% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00759/21	Poland	Plastic Doll with Accessories (Country of Origin: Unknown)		Chemical The plastic material of the product contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 10% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00760/21	Poland	Plastic Doll with Accessories (Country of Origin: Unknown)		Chemical The plastic material of the product contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 8.6% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00761/21	Poland	Plastic Doll with Accessories (Country of Origin: Unknown)		Chemical The plastic material of the toy contains an excessive amount of di-'isononyl' phthalate (DINP) (measured value: up to 0.23% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system and liver. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00763/21	Poland	Set of Plastic Dolls with Accessories (Country of Origin: China)		Chemical The plastic material of the product contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 19% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00764/21	Poland	Set of Plastic Dolls with Accessories (Country of Origin: China)		Chemical The plastic material of the toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 21% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00765/21	Poland	Remote-Controlled Toy Car (Country of Origin: Unknown)		Chemical The plastic material of the toy contains an excessive amount of benzyl butyl phthalate (BBP), diisodecyl phthalate (DIDP) and di-n-octyl phthalate (DNOP) (measured values: up to 0.32%, 0.56% and 0.21% by weight respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border





The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00766/21	Poland	Set of Plastic Dolls with Accessories (Country of Origin: China)		Chemical The plastic material of the toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 17% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00767/21	Bulgaria	Sleep Bag (Country of Origin: Bulgaria)		Choking The puller of the slide fastener (zip) could detach as a small part. A child could put it in the mouth and choke. The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 16781:2018.	Withdrawal of the product from the market
A12/00772/21	Poland	Plastic Doll (Country of Origin: Unknown)		Chemical The plastic material of the toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 11.4% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00780/21	Iceland	Children's Swing (Country of Origin: Unknown)		Injury The knots of the rope may come loose, causing the rope to detach from the seat. As a result, a child may fall off the seat and suffer from injuries. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-8.	Recall of the product from end users






The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00782/21	Poland	Expandable Toy (Country of Origin: China)		Choking, Injury The expanding material increases in size by more than 50% when placed in water. The toy can be put into the mouth and swallowed by children. As the toy expands, it can cause fatal occlusion of the respiratory track or intestinal blockage in small children. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/00786/21	Poland	Expandable Toy (Country of Origin: China)		Choking, Injury The expanding material increases in size by more than 50% when placed in water. The toy can be put into the mouth and swallowed by children. As the toy expands, it can cause fatal occlusion of the respiratory track or intestinal blockage in small children. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/00787/21	Poland	Expandable Toy (Country of Origin: China)		Choking, Injury The expanding material increases in size by more than 50% when placed in water. The toy can be put into the mouth and swallowed by children. As the toy expands, it can cause fatal occlusion of the respiratory track or intestinal blockage in small children. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market




The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00792/21	Poland	Plastic Doll with Accessories (Country of Origin: China)		Chemical The plastic material of the product contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP), di-'isononyl' phthalate (DINP) and dibutyl phthalate (DBP) (measured values: up to 4.72%, 3.26% and 0.27% by weight respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system and liver. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00793/21	Poland	Jumping Ball (Country of Origin: China)		Chemical The plastic material of the product contains an excessive amount of diisobutyl phthalate (measured value up to: 37.67% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00794/21	Poland	Set of Plastic Dolls with Accessories (Country of Origin: China)		Chemical The plastic material of the toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: up to 14.3% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border
A12/00795/21	Poland	Set of Plastic Dolls with Accessories (Country of Origin: China)		Chemical The plastic material of the toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values: 11.86% and 0.11% by weight respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border





The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00796/21	Poland	<p>Plastic Doll with Accessories</p> <p>(Country of Origin: China)</p>		<p>Chemical</p> <p>The plastic material of the toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 10.4% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.</p>	Import rejected at border
A12/00797/21	Poland	<p>Plastic Doll with Accessories</p> <p>(Country of Origin: China)</p>		<p>Chemical</p> <p>The plastic material of the toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 36.6% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.</p>	Import rejected at border
A12/00798/21	Poland	<p>Set of Plastic Dolls with Accessories</p> <p>(Country of Origin: China)</p>		<p>Chemical</p> <p>The plastic material of the toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 1.3% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.</p>	Import rejected at border
A12/00799/21	Poland	<p>Set of Plastic Dolls with Accessories</p> <p>(Country of Origin: China)</p>		<p>Chemical</p> <p>The plastic material of the toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: 33.3% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.</p>	Import rejected at border
A12/00801/21	Belgium	<p>Baby Nest</p> <p>(Country of Origin: Unknown)</p>		<p>Strangulation</p> <p>The drawstrings at the bottom of the product are too long when tightened. Baby's head can be trapped by the drawstrings, leading to strangulation. The product does not comply with the requirements of the General Product Safety Directive and the relevant European Standards EN 16890, EN 16780, EN 16781 and EN 1466.</p>	Recall of the product from end users





The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A11/00041/21	France	Play Frame with Slide and Swings (Country of Origin: China)		Entrapment, Injury The toy has partially closed openings and accessible holes (between the seat and the backrest of the face-to-face swing) in which children can be trapped or suffer from injuries. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-8.	Recall of the product from end users
A12/00815/21	Cyprus	Toys (Country of Origin: China)		Chemical The rubber of the toys releases an excessive amount of nitrosamines (measured total value: 0.06 mg/kg), which contain n-nitrosodimethylamine (NDMA). Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching the product or putting it in the mouth. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-12.	Withdrawal of the product from the market
A12/00816/21	Cyprus	Balloons (Country of Origin: China)		Chemical The rubber of the balloons releases an excessive amount of nitrosamines (measured total value: 0.41 mg/kg) and nitrosatable substances (measured total value: 1.82 mg/kg), which generate nitrosamines that contain N-Nitrosodiethylamine (NDEA) and n-nitrosodimethylamine (NDMA). Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching the product or putting it in the mouth. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-12.	Withdrawal of the product from the market




The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00818/21	Luxembourg	Baby Nest (Country of Origin: France)		Injury, Strangulation, Suffocation The drawstrings at the bottom of the product are too long when tightened. Baby's head can be trapped by the drawstrings, leading to strangulation. Furthermore, there are several gap openings that can increase the risk of the baby's mouth and nose being completely covered, causing suffocation. The product does not comply with the requirements of the General Product Safety Directive and the relevant European Standards EN 16890, EN 16780, EN 16781 and EN 1466.	Ban on the marketing of the product and any accompanying measures
A12/00831/21	Sweden	Balloons (Country of Origin: Spain)		Chemical The rubber of the dark blue balloons releases an excessive amount of N-nitrosamines (measured value: 0.076 mg/kg), which contain n-nitrosodiethanolamine (NDELA). Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching the product or putting it in the mouth. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-12.	Withdrawal of the product from the market
A12/00832/21	Finland	Plastic Building Blocks Set (Country of Origin: Turkey)		Choking The product contains small parts (leaves of the tree). A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Import rejected at border
A12/00833/21	Finland	Toy Helicopter (Country of Origin: Turkey)		Choking Small parts (wheels of the helicopter) can detach from the toy. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Import rejected at border





The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00839/21	Belgium	Toy Drum (Country of Origin: China)		Choking Small parts (the side springs) can easily detach from the toy. A small child may put it in the mouth and choke. The product does not comply with the requirements of the General Product Safety Directive and European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A12/00841/21	Poland	Flashing Yoyo Ball (Country of Origin: China)		Strangulation The toy is elastic and can be considerably stretched during use. A child could swing the toy around the head and twist it around the neck, causing strangulation. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/00849/21	Finland	Baby Nest (Country of Origin: China)		Choking, Strangulation The product has long cords that can cause strangulation to a baby. It also has small detachable parts which children can easily access, put in the mouth and choke on, causing an additional risk of infection if the small parts get into the respiratory tract of the children. The product does not comply with the requirements of the General Product Safety Directive and the standards EN 16890, EN 16780 and EN 16781.	Warning consumers of the risks
A12/00850/21	Germany	Baby's Sleep Suit (Country of Origin: China)		Chemical The product releases an excessive amount of nickel (calculated value: 1.86 µg/cm ² /week). Nickel is a strong sensitizer and causes allergic reactions if present in articles that come into direct and prolonged contact with the skin. The product does not comply with the REACH Regulation.	Warning consumers of the risks





The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00858/21	Cyprus	Balloons (Country of Origin: China)		Chemical The rubber of the balloons releases an excessive amount of nitrosamines (measured total value: 0.16 mg/kg) and nitrosatable substances (measured total value: 1.84 mg/kg), which generate nitrosamines that contain n-nitrosodiethylamine (NDEA) and n-nitrosodimethylamine (NDMA). Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching the product or putting it in the mouth. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-12.	Withdrawal of the product from the market
A12/00859/21	Cyprus	Finger Paint (Country of Origin: China)		Chemical The red and green finger paints release an excessive amount of nitrosamines (measured values: up to 0.19 mg/kg), which contain n-nitrosodiethanolamine (NDELA). Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching the product or putting it in the mouth. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-12.	Withdrawal of the product from the market
A12/00864/21	Cyprus	Babies' Rattle (Country of Origin: China)		Choking Small parts (the balls) can easily detach from the rattle. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Withdrawal of the product from the market




The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00871/21	Cyprus	Toy Keyboard (Country of Origin: China)		Choking Small parts (black keys) can easily detach from the toy. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/00873/21	Luxembourg	Sleep Bag for Babies (Country of Origin: France)		Entrapment, Injury, Suffocation The top stop of the slide fastener (zip) at the arm opening is placed on the top instead of bottom of the product. Furthermore, the neck opening is too large in relation to the child height or age. This can increase the risk of a baby slipping inside the sleep bag and suffocating. In addition, as there are loops (a bow and a loop label) on the sleep bag, the baby's finger could be trapped in the bow. The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 16781:2018.	Temporary ban on the supply, offer to supply and display of the product
A12/00874/21	Cyprus	Doll Pushchair (Country of Origin: China)		Injury The pushchair is not sufficiently resistant to load. As a consequence, it can easily collapse and a child playing with it may fall to the ground. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/00875/21	Cyprus	Doll Pushchair (Country of Origin: China)		Injury The pushchair is not sufficiently resistant to load. As a consequence, it can easily collapse and a child playing with it may fall to the ground. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market


The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00877/21	Sweden	Pushchair (Country of Origin: China)		Injury The pushchair is not stable and can tip over unexpectedly. This can cause the child sitting in it to fall off and suffer from injuries. The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 1888-1.	Recall of the product from end users
A12/00882/21	France	Baby's Soother (Country of Origin: China)		Chemical The product contains Bisphenol A (BPA) (measured value: 2.3 mg/kg). BPA may damage fertility and has been identified as a substance affecting the hormonal systems of humans and animals. The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 1400.	Removal of this product listing by the online marketplace
A12/00896/21	Poland	Infant Swing (Country of Origin: China)		Suffocation Infants who are placed unrestrained in the product and later found on their stomach are at risk of suffocation. The product does not comply with the requirements of the General Product Safety Directive.	Withdrawal of the product from the market
A12/00898/21	Luxembourg	Children's Car Seat (Country of Origin: China)		Injury In the event of a car-crash, the car seat may not properly restrain the child to minimize the displacement of the body. As a consequence, the child could be injured. Furthermore, compulsory information about the installation of the child in the seat is uncomplete leading to a possible wrong installation and increasing the risk of injuries. The product does not comply with Regulation UN/ECE No 44-04.	Recall of the product from end users

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00899/21	Austria	<p>Magazine with a Bow and 3 Arrows</p> <p>(Country of Origin: Germany)</p>		<p>Choking</p> <p>Some suction cups can be easily detached. If a child puts them in the mouth, the suction cups could detach and obstruct the airway of the child. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.</p>	<p>Withdrawal of the product from the market</p>
A12/00902/21	Luxembourg	<p>Baby Nest</p> <p>(Country of Origin: Portugal)</p>		<p>Entrapment, Injury, Strangulation, Suffocation</p> <p>If the head of a baby is placed towards the wrong direction, the baby may get trapped in the gap opening. Because of horizontal gaps, the bumper part may cover the baby's mouth and nose, causing suffocation. The product has long cords that can cause injuries and strangulation. Furthermore, the product is not accompanied by any purchase information, warnings, nor instructions for use. The product does not comply with the requirements of the General Product Safety Directive and the standards EN 16890, EN 16780 and EN 16781.</p>	<p>Temporary ban on the supply, offer to supply and display of the product</p>
A12/00908/21	Czechia	<p>Finger Paint</p> <p>(Country of Origin: Hong Kong)</p>		<p>Chemical</p> <p>The blue finger paint releases an excessive amount of nitrosamines (measured total value: 60.14 mg/kg), which contain 4-nitrosomorpholine (NMOR) and n-nitrosodiethanolamine (NDELA). Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching the product or putting it in the mouth. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-12.</p>	<p>Withdrawal of the product from the market</p>

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00926/21	Poland	Toy Tent (Country of Origin: China)		Burns, Cuts, Injury The material of the tent is easily flammable and the flame propagation is too high. If it catches fire, the child will likely suffer from burns. Furthermore, the tent's frame is not sufficiently stable and can break when using the product. This could lead to injuries or cuts with the sharp edges. The product does not comply with the Toy Safety Directive and the relevant European standards EN 71-1 and EN 71-2.	Withdrawal of the product from the market
--------------	--------	--------------------------------------------------------------	-----------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------

Safety Gate: the EU rapid alert system for dangerous non-food products






“Safety Gate”, the EU rapid alert system (formerly known as ‘RAPEX’), enables the rapid exchange of information between 31 European countries and the European Commission on non-food dangerous products found on the market posing a risk to health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on <https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports>. The measures taken in the notifying country in order to restrict their marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").



The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC), responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

Recall Summary – US Toys / Children’s Products

CPSC Recall List (May 2021)

Recall No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
21-147	USA	Fisher-Price 4-in-1 Rock ‘n Glide Soothers and 2-in-1 Soothe ‘n Play Gliders (Country of Origin: Unknown)		Risk of Suffocation Infants who are placed unrestrained in the product and later found on their stomach are at risk of suffocation.	Refund
21-754	USA	Children’s Barhee Fishing Hero Toy Games (Country of Origin: China)		Lead Toxic The metal rollers at the bottom of the flying dinosaur figures contain levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young children and it can cause adverse health issues.	Consumers should immediately take the recalled toys away from children and contact Blue Star Trading for a full refund. Blue Star Trading is contacting all purchasers directly.
21-757	USA	Girls’ Nightgowns (Country of Origin: China)		Risk of Burn The recalled children’s nightgowns fail to meet flammability standards for children’s sleepwear, posing a risk of burn injuries to children.	Consumers should immediately stop using the recalled children’s nightgowns and contact La Paloma for a full refund. La Paloma is contacting all known purchasers directly.
21-156	USA	Children’s Nightgowns (Country of Origin: China)		Risk of Burn The nightgowns fail to meet the federal flammability standards for children’s sleepwear, posing a risk of burn injuries to children.	Consumers should immediately stop using the recalled garments and contact Auranso Official for instructions on returning the garments with free shipping to receive a full refund.
21-157	USA	Children’s Nightgowns (Country of Origin: China)		Risk of Burn The nightgowns fail to meet the federal flammability standards for children’s sleepwear, posing a risk of burn injuries to children.	Consumers should immediately stop using the recalled garments and contact Booph for instructions on returning the garments with free shipping to receive a full refund.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

21-158	USA	<p>UPPAbaby Adapters Included with Rumbleseats</p> <p>(Country of Origin: China)</p>		<p>Fall Hazard</p> <p>The adapters can detach, posing a fall hazard to the child in the RumbleSeat.</p>	<p>Consumers who own a RumbleSeat accessory, manufactured between September 2014 and July 2019, will be provided with replacement RumbleSeat adapters. Consumers should immediately stop using the recalled adapters and contact UPPAbaby to receive free replacement adapters.</p>
21-159	USA	<p>Children’s Robes</p> <p>(Country of Origin: China)</p>	<p>Recalled SIORO children’s robe - white</p> 	<p>Risk of Burn</p> <p>The children’s robes fail to meet the federal flammability standards for children’s sleepwear, posing a risk of burn injuries to children.</p>	<p>Consumers should immediately stop using the recalled garments and contact SIORO for instructions on returning the garments with free shipping to receive a full refund.</p>

*Source: www.recalls.gov

CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a “one stop shop” for U.S. Government recalls, www.recalls.gov, has been created. Publics can report unsafe products to CPSC by using the platform.




The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall was conducted, voluntarily by the company, under CPSC’s Fast Track Recall program. Fast Track recalls are initiated by firms who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.

Recall Summary – Australia Toys / Children’s Products



ACCC Recall List (Jun 2021)

PRA No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
2021/18905	Australia	Baby Sleep Pouch in Beach Forest and Sweet Dreams Print Designs		Entrapment Hazard The sleep pouch neck opening is wider than necessary. This opening could allow an infant to pull the pouch over their head and may pose an entrapment hazard. If the child becomes trapped in the pouch, this increases the risk of suffocation or the child may overheat.	Consumers should immediately stop using the product and return the product to Halcyon Nights for an exchange or full refund.
2021/18960	Australia	Mammakiddies Car Booster Seat		Risk of Injury The product does not meet the requirements of the mandatory standard ‘Consumer Protection Notice No. 3 of 2014 - Child restraint systems for use in motor vehicles. Child seats without the correct safety warning label may be used incorrectly, posing an increased risk of serious injury or death to the occupant if the vehicle is in an accident.	Consumers should return the product to Pharmrec Trading for a full refund.
2021/18959	Australia	Kids Tricycle with Parent Handle		Injury These products have some of the features of a pushchair, but are unsafe for use as a pushchair to transport children as they do not have the safety features required under the mandatory standard ‘Consumer Product Safety Standard for Prams and Strollers (Consumer Protection Notice No. 8 of 2007, as amended on 14 February 2019)’.	Consumers should not use the product as a stroller to transport children. Consumers should return the product to the place of purchase for a refund or replacement.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

2021/18987	Australia	<p>Kids Licensed Paw Patrol Digital Watch</p>		<p>Choking Hazard The button battery compartment of the product may not be adequately secured, so the button battery in the product may be easily accessible.</p> <p>If young children gain access to the button battery and ingest it, they may suffer from internal burn injuries, which can result in serious illness and even death. In addition, the battery may pose a choking hazard to young children.</p>	<p>Consumers should immediately cease using the product and return the product to the place of purchase for a full refund.</p>
2021/19008	Australia	<p>Thankyou Thick & Soft Baby Wipes Value Pack</p> <p>3 Packs of 80 Wipes</p>	 <p>Thick & Soft Baby Wipes 3x 80 pack</p>	<p>Risk to Allergic to Penicillin Wipes with the affected timestamp within the affected batch of baby wipes was manufactured without preservative. As a result, mold may grow on the baby wipes.</p> <p>Exposure to penicillin within the mold spores may cause an adverse reaction or health complications. This may pose a risk to people allergic to penicillin, people with weakened immune systems or those with sensitive skin, including babies.</p>	<p>Consumers should stop using products from the affected batch and contact Thankyou Group for a full refund. Consumers will be asked to provide a photograph of the product, if possible, before disposing of the product.</p>
2021/19049	Australia	<p>Baby Carriage - 3 in 1 Baby Carriage Bassinet with Pushchair Set</p> <p>Baby Carriage - 3 in 1 Bassinet + Baby Carriage Set</p>		<p>Risk of Injury The stroller does not comply with the mandatory standard 'Consumer Product Safety Standard for Prams and Strollers (Consumer Protection Notice No. 8 of 2007, as amended on 14 February 2019)'.</p> <p>If the product does not have the required safety features, the product may not be used correctly, posing a risk of injury to the child.</p>	<p>Consumers will be contacted by Cuteably to arrange for instructions and a Red Brake Actuator Cover to be sent to them. The Red Brake Actuator Cover should be installed over the black brake actuator.</p>

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

2021/19051	Australia	<p>Customizable Dummy Chain and Teether Sets</p> <p>Available in 16 Different Designs and 8 Colors</p>		<p>Strangulation Hazard</p> <p>The dummy chain does not comply with the Australian mandatory standard ‘Consumer Goods (Babies Dummies and Dummy Chains) Safety Standard 2017’.</p> <p>The dummy chain may get caught around an infant / child’s throat and pose a strangulation hazard.</p>	<p>Consumers should stop using the dummy chain until they have checked the length of the chain. If the dummy chain is longer than 22cm, consumers should return the product to the supplier to receive a replacement.</p>
2021/19079	Australia	<p>Sleepwear for Infants</p> <p>Size 0 – 6 Months</p> <p>Various Styles and Patterns</p>		<p>Entrapment Hazard</p> <p>The size of the product’s neck opening is too large and may allow a baby to slip down into the garment, covering the baby’s face or posing an entrapment hazard.</p> <p>If a baby’s face is covered by the garment or the child becomes trapped, there is an increased risk of suffocation, which can lead to severe injury or death.</p>	<p>Consumers should immediately stop using the product and return it to their nearest TK Maxx store for a full refund or store credit.</p>

Australian Product Safety System

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <https://www.productsafety.gov.au/recalls>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 50 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but not limited to:

EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethylfumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 – DEHP

FOR MORE DETAILS, PLEASE CONTACT US :

Hong Kong: hktcd@stc.group
Changzhou: czstc@stc.group
U.S.A.: usstc@stc.group

Dongguan: dgtcd@stc.group
Vietnam: vnstc@stc.group
Germany: grstc@stc.group

Shanghai: shtcd@stc.group
Japan: jpo@stc.group



The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.